

TEAM _____

Vehicle No:	SMR5866L (Insd veh)	Model:	BMW X3 2.0 I SDRIVE (A)
	SJU6279U (TP veh)		
Date of Accident:	21/10/2020		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$	6,237.46	
Final Repair Cost	: \$	3,834.24	
Loss of Use	: \$	300.00	3.00 days at \$100.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	2.00	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	4,136.24	
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u>:		Agreed Liability _____ (%)	
B) For <u>GIA Registered Workshop</u>:		BOLA Applicable: Yes/ No BOLA Scenario No: _____ _27_	
BOLA Liability: ____ 100 ____ (%)		Assessed Liability (*): _____ (%)	
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>			
Remarks _____ _____ _____			

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	: \$	4,136.24
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN	15 Jan 2021
LKK Auto Consultants Pte Ltd	Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))