



S THREE AUTOMOTIVE RECOVERY PTE LTD

Not Authorized
6 Days @ 8700p
Presumably After Paim
9 days

0
TIN: MOTOR CLAIM DEPT. T/P VEH NO: TRC2849B

ESTIMATE REPORT 1st QUOTATION

OWNER'S PARTICULAR

NAME: HO CHU LAN

ADDRESS:

JOB NO:

CONTACT:

LICENSE NO: SJP5750H

TRANS.:

MAKE / MODEL: HYUNDAI AVANTE

OWNER'S INSURER: BUDGET ASIA

OB-CODE: TP

S/A: MICHELLE

CHASSIS NO:

ENGINE NO:

ACCIDENT DATE: 20-Oct-20

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR-DISC	REV. PRICE
1 FRONT BUMPER	1.00	\$ 566.00	20.00	\$ 452.80	Y	✓
2 FRONT BUMPER SIDE RETAINER RH	1.00	\$ 27.00	20.00	\$ 21.60	Y	✓
3 FRONT BUMPER SIDE RETAINER LH	1.00	\$ 27.00	20.00	\$ 21.60	Y	X
4 FRONT HEADLAMP RH	1.00	\$ 489.50	20.00	\$ 391.60	Y	✓
5 FRONT BUMPER FOG LAMP RH	1.00	\$ 385.00	20.00	\$ 308.00	Y	X
6 FRONT WING MIRROR RH	1.00	\$ 358.00	20.00	\$ 286.40	Y	✓
7 FRONT DOOR RH	1.00	\$ 1,070.00	20.00	\$ 856.00	Y	✓
8 FRONT DOOR FRAME RH	1.00	\$ 21.00	20.00	\$ 16.80	Y	✓
9 FRONT FENDER RH	1.00	\$ 389.00	20.00	\$ 311.20	Y	✓
10 FRONT DOOR OUTER MOULDING RH	1.00	\$ 48.00	20.00	\$ 38.40	Y	X
11 FRONT DOOR HINGE UPPER RH	1.00	\$ 188.00	20.00	\$ 150.40	Y	X
12 FRONT DOOR HINGE LOWER RH	1.00	\$ 188.00	20.00	\$ 150.40	Y	X
13 FRONT DOOR GLASS CHANNEL RH	1.00	\$ 111.00	20.00	\$ 88.80	Y	X
14 FRONT DOOR LOCK RH	1.00	\$ 238.00	20.00	\$ 190.40	Y	✓
15 FRONT DOOR HANDLE RH	1.00	\$ 46.00	20.00	\$ 36.80	Y	✓
16 FRONT DOOR INNER HANDLE RH	1.00	\$ 37.00	20.00	\$ 29.60	Y	X
17 FRONT DOOR RUBBER BEADING RH	1.00	\$ 118.00	20.00	\$ 94.40	Y	X
18 FRONT DOOR TRIM BOARD RH	1.00	\$ 586.00	20.00	\$ 468.80	Y	X
19 FRONT DOOR CHECK LINK RH	1.00	\$ 48.00	20.00	\$ 38.40	Y	X
20 FRONT DOOR TOP FRAME RUBBER BEADING RH	1.00	\$ 21.00	20.00	\$ 16.80	Y	X
21 FRONT DOOR GLASS REGULATOR RH	1.00	\$ 238.00	20.00	\$ 190.40	Y	X
22 FRONT DOOR GLASS MOTOR RH	1.00	\$ 210.00	20.00	\$ 168.00	Y	X
23 FRONT SHOCK ABSORBER RH	1.00	\$ 187.00	20.00	\$ 149.60	Y	✓
24 FRONT SHOCK ABSORBER LH	1.00	\$ 187.00	20.00	\$ 149.60	Y	✓
25 FRONT KNUCKLE ARM RH	1.00	\$ 352.00	20.00	\$ 281.60	Y	✓
26 FRONT KNUCKLE ARM LH	1.00	\$ 352.00	20.00	\$ 281.60	Y	✓
27 FRONT LOWER ARM RH	1.00	\$ 279.00	20.00	\$ 223.20	Y	✓
28 FRONT LOWER ARM LH	1.00	\$ 279.00	20.00	\$ 223.20	Y	✓
29 FRONT KNUCKLE ARM BEARING RH	1.00	\$ 111.00	20.00	\$ 88.80	Y	✓
30 FRONT KNUCKLE ARM BEARING LH	1.00	\$ 111.00	20.00	\$ 88.80	Y	✓
31 REAR BUMPER	1.00	\$ 442.00	20.00	\$ 353.60	Y	X

32	REAR BUMPER INNER SPONGE	Pu	1.00	\$	122.00	20.00	\$	97.60	Y	X
33	REAR BUMPER REINFORCEMENT	N	1.00	\$	262.00	20.00	\$	209.60	Y	X
34	REAR BUMPER REINFORCEMENT STAY	Sn	2.00	\$	134.80	20.00	\$	107.84	Y	X
35	REAR BUMPER SUPPORT BRACKET	Ln	4.00	\$	114.00	20.00	\$	91.20	Y	X
36	REAR BUMPER SIDE RETAINER LH	Ln	1.00	\$	42.50	20.00	\$	34.00	Y	X
37	REAR BUMPER SIDE RETAINER RH	Sn	1.00	\$	42.50	20.00	\$	34.00	Y	X
38	REAR TAILLAMP RH	Gt	1.00	\$	294.00	20.00	\$	235.20	Y	✓
39	REAR DOOR RH	Bt	1.00	\$	947.20	20.00	\$	757.76	Y	✓
40	REAR DOOR SIDE INNER RUBBER SEAL RH	Pu	1.00	\$	131.00	20.00	\$	104.80	Y	X
41	REAR DOOR FRAME RH	Nu	1.00	\$	28.00	20.00	\$	22.40	Y	✓
42	REAR DOOR OUTER MOULDING CHROME RH	Sn	1.00	\$	48.00	20.00	\$	38.40	Y	X
43	REAR DOOR LOCK RH	N	1.00	\$	389.00	20.00	\$	311.20	Y	X
44	REAR DOOR REGULATOR RH	Nt R	1.00	\$	280.00	20.00	\$	224.00	Y	✓
45	REAR DOOR REGULATOR MOTOR RH	Tm	1.00	\$	210.00	20.00	\$	168.00	Y	✓
46	REAR DOOR TRIMBOARD RH	Sn	1.00	\$	414.00	20.00	\$	331.20	Y	X
47	REAR DOOR CHECK LINK RH	Sn	1.00	\$	68.00	20.00	\$	54.40	Y	X
48	REAR DOOR OUTER HANDLE RH	Ln	1.00	\$	95.80	20.00	\$	76.64	Y	X
49	REAR DOOR RUBBER BEADING RH	Sn	1.00	\$	131.00	20.00	\$	104.80	Y	X
50	REAR DOOR HINGE UPPER RH	N	1.00	\$	188.00	20.00	\$	150.40	Y	X
51	REAR DOOR HINGE LOWER RH	N	1.00	\$	188.00	20.00	\$	150.40	Y	X
52	REAR WHEEL HUB BEARING RH	na	1.00	\$	332.00	20.00	\$	265.60	Y	X
53	REAR WHEEL HUB BEARING LH	Rt/Na	1.00	\$	332.00	20.00	\$	265.60	Y	X 2
54	REAR LOWER ARM RH	Ln	1.00	\$	278.00	20.00	\$	222.40	Y	X
55	REAR LOWER ARM LH	Nt	1.00	\$	278.00	20.00	\$	222.40	Y	2
56	REAR UPPER ARM RH	Ln	1.00	\$	206.00	20.00	\$	164.80	Y	X
57	REAR UPPER ARM LH	Spn	1.00	\$	206.00	20.00	\$	164.80	Y	X
58	REAR SHOCK ABSORBER RH	Ln	1.00	\$	219.00	20.00	\$	175.20	Y	X
59	REAR SHOCK ABSORBER LH	Bt	1.00	\$	219.00	20.00	\$	175.20	Y	2
60	REAR KNUCKLE ARM RH	Bt	1.00	\$	480.00	20.00	\$	384.00	Y	2
61	REAR KNUCKLE ARM LH	Bt	1.00	\$	480.00	20.00	\$	384.00	Y	2
62	CENTRE PILLAR	N	1.00	\$	128.00	20.00	\$	102.40	Y	X
63	KEY LOCK	SVC	1.00	\$	108.00	20.00	\$	86.40	Y	X
TOTAL (PARTS):					\$ 13,016.80	\$ 10,413.44				

SPECIAL NETT ITEM

1	FRONT BUMPER CLIPS	Nu	1.00	\$	50.00	0.00	\$	50.00	Y	✓
2	REAR BUMPER CLIPS	Nu	1.00	\$	50.00	0.00	\$	50.00	Y	✓
4	FRONT DOOR FRAME STICKER RH	Nu	1.00	\$	80.00	0.00	\$	80.00	Y	✓
5	FRONT DOOR INSULATOR PAD RH	Nu	1.00	\$	280.00	0.00	\$	280.00	Y	X
6	FRONT FENDER INNER SHIELD	Sn	1.00	\$	80.00	0.00	\$	80.00	Y	X
7	FRONT SPORT RIM RH	Ru	1.00	\$	680.00	0.00	\$	680.00	Y	250.00

- 8 FRONT SPORT RIM LH
9 FRONT TYRE RH
10 FRONT TYRE LH
11 REAR SPORT RIM RH
12 REAR SPORT RIM LH
13 REAR TYRE RH
14 REAR TYRE LH

<i>Ref</i>	1.00	\$	680.00	0.00	\$	680.00	Y	<i>2501n</i>
<i>Sn</i>	1.00	\$	280.00	0.00	\$	280.00	Y	<i>X</i>
<i>Sn</i>	1.00	\$	280.00	0.00	\$	280.00	Y	<i>X</i>
<i>Sn</i>	1.00	\$	680.00	0.00	\$	680.00	Y	<i>X</i>
<i>Ref</i>	1.00	\$	680.00	0.00	\$	680.00	Y	<i>2501n</i>
<i>Sn</i>	1.00	\$	280.00	0.00	\$	280.00	Y	<i>X</i>
<i>Sn</i>	1.00	\$	280.00	0.00	\$	280.00	Y	<i>X</i>

TOTAL (PARTS):

\$ 4,280.00 \$ 4,280.00

LABOUR

- 1 STRAIGHTEN & PANEL BEAT ACCIDENT AREA
2 SPRAY PAINTING ON ACCIDENT AREA
3 RESPRAY TUFF KOTE ON ACCIDENT AREA
4 CONDUCT FULL WHEEL ALIGNMENT
5 CHECK WIRING SYSTEM
6 R&R FRONT UNDERCARRIAGE SYSTEM
7 R&R REAR UNDERCARRIAGE SYSTEM
8 R&R FRONT DOOR COMPARTMENT RH
9 R&R REAR DOOR COMPARTMENT RH

1.00	\$	1,800.00	0.00	\$	1,800.00	Y	<i>800</i>
1.00	\$	1,600.00	0.00	\$	1,600.00	Y	<i>1000</i>
1.00	\$	180.00	0.00	\$	180.00	Y	<i>901</i>
1.00	\$	120.00	0.00	\$	120.00	Y	<i>801</i>
1.00	\$	180.00	0.00	\$	180.00	Y	<i>401</i>
1.00	\$	380.00	0.00	\$	380.00	Y	<i>2401</i>
1.00	\$	380.00	0.00	\$	380.00	Y	<i>1801</i>
1.00	\$	120.00	0.00	\$	120.00	Y	<i>601</i>
1.00	\$	120.00	0.00	\$	120.00	Y	<i>601</i>

TOTAL (LABOUR):

\$ 4,880.00 \$ 4,880.00

TOTAL PARTS & LABOUR

\$ 22,176.80 \$ 19,573.44

EXCESS: : \$\$

NO. OF DAY : *08*

RE-SURVEY : ~~BEFORE~~ / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : \$\$

DATE OF SURVEY : *22, 10, 20*

SURVEY BY : *Kenneth*

CONTACT NO: _____

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



S THREE AUTOMOTIVE RECOVERY PTE LTD

TO :
ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : TRC2849B

ESTIMATE REPORT 1st QUOTATION
OWNER'S PARTICULAR

JOB NO. : _____

NAME : HO CHU LAN
ADDRESS : _____

CONTACT : _____

LICENSE NO. SJP5750H TRANS. :
MAKE / MODEL : HYUNDAI AVANTE
OWNER'S INSURER : BUDGET ASIA
JOB-CODE : TP S/A : MICHELLE

CHASSIS NO :
ENGINE NO :

ACCIDENT DATE : 20-Oct-20

SUPPLYMENTARY

1	WASHER TANK	Sm	1.00	\$	105.00	20.00	\$	84.00	Y	X
2	FRONT FOG LAMP COVER RH	Sm	1.00	\$	120.00	20.00	\$	96.00	Y	X
3	FRONT DOOR HANDLE INNER HOUSING RH	nd	1.00	\$	320.00	20.00	\$	256.00	Y	✓
4	FRONT FENDER EMBLEM VVTI	nd	1.00	\$	52.00	20.00	\$	41.60	Y	✓
5	FRONT FENDER INNER SHIELD RH	Sm	1.00	\$	158.00	20.00	\$	126.40	Y	X
6	REAR BUMPER RETAINER RH	Dr	1.00	\$	42.50	20.00	\$	34.00	Y	✓
7	REAR DOOR GLASS RH	Sm	1.00	\$	294.00	20.00		235.2	Y	X
8	FRONT SUPPORT PANEL	cm	1.00	\$	753.00	20.00		602.4	Y	✓

\$ 1,844.50

\$ 1,475.60

EXCESS : : S\$ _____

NO. OF DAY : _____

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : S\$ _____

DATE OF SURVEY : ____/____/____

SURVEY BY : _____

CONTACT NO : _____

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.