



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD			Ref: CC4/ASM20011457/Uba3q2 Date: 20/08/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBR 693G	Veh. Inspected	GBB 301Y
	Policy No.	P2383985	Coverage (\$)	0.00
	Claim No.	S0M02VSK	Excess (\$)	0.00
	Assign From		Assign Date	21/10/2020
2. Vehicle Particulars & Condition				
	Make & Model	mitsubishi CANTER FB70 (M)	c.c	2977
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	FB70BBA10489	Colour	WHITE
	Odometer	245328 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	BRIDGESTONE	6 mm
	L/H Front Tyre	195 R15	BRIDGESTONE	6 mm
	R/H Rear Tyre	195 R15 (D)	OHTSU	6/6 mm
	L/H Rear Tyre	195 R15 (D)	OHTSU	6/6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/10/2020	Inspection Date	22/10/2020
	Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 37A EVERITT ROAD SINGAPORE 428586		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	