

ESTIMATE TO REPAIR

VEHICLE NO. : SKA 3127 M
MAKE : BMW
MODEL : X6 3.0 A
YEAR : 2010
CHASSIS NO : WBAFG22070LL80464

SURVEYOR NAME : LKK
DATE OF SURVEY : 4-NOV
TIME OF SURVEY : 2pm

DATE : 25-Oct-20
DATE OF ACCIDENT : 21-Oct-20
THIRD PARTY REF : SML 425 R
THIRD PARTY REF : AIG ASIA PACIFIC INSURANCE PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
	To Putty & Spray Paint				\$ 800.00
	Labour charges.				\$ 300.00
TG/SO	TOTAL				\$ 1,100.00
<p><i>Not Authorised Repair After Paint 3 days</i></p> <p>P/P = \$760.00</p> <div> LKK Auto Consultants hence notify the Repairer of the following: <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p> </div>					
TG/VL	TOTAL				\$ -

Lim Tan Motor Pte Ltd
Bik 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64589127 Email: edmund@ltm.sg
Co Reg No 199307277D GST Reg No M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd