

# LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645  
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721  
 Tel No. : 64534177 Fax No. : 64593724  
 E-Mail : limyewboo@singnet.com.sg  
 Website : www.limyewboo.com.sg  
 Buss. Reg. No. : 200514/00L

INDIA INTERNATIONAL INSURANCE PTE LTD  
 64 CECIL STREET #05-00  
 IOB BUILDING SINGAPORE 049711

Attention : Motor Claim Department  
 Contact : 63476100 Fax No. : 62244174

Estimate : TP20/036

Date : 22/10/2020  
 Vehicle Num. : ES 3383R  
 Make/Model : LEXUS RX 270-2012  
 Chassis/Eng# : JTJZA11A302018933/1AR0776588  
 Accident Date : 22/10/2020  
 Claim No. :  
 Reference : LYB/ES3383R/III/tp/sl  
 Policy No. :

*Not Authorised*

*6/10/20*

*Runny After Rain*

*4 days*

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

| S/N                                                                                                              | Quantity | Particular                      | Unit Price | Amount S\$ |
|------------------------------------------------------------------------------------------------------------------|----------|---------------------------------|------------|------------|
| <b>LIST ITEMS :</b>                                                                                              |          |                                 |            |            |
| 1.                                                                                                               | 1        | FRONT BUMPER                    |            |            |
| 2.                                                                                                               | 1        | FRONT BUMPER RETAINER/LH        |            |            |
| 3.                                                                                                               | 1        | FRONT FENDER/LH                 |            |            |
| 4.                                                                                                               | 1        | FRONT FENDER INNER SHIELD/LH    |            |            |
| 5.                                                                                                               | 1 SET    | FRONT FENDER INNER SHIELD CLIPS |            |            |
| 6.                                                                                                               | 1        | FRONT HEADLAMP ASSY/LH          |            |            |
| 7.                                                                                                               | 1        | FRONT FOG LAMP COVER/LH         |            |            |
| List Total S\$ :                                                                                                 |          |                                 |            | 6,263.90   |
| 20.00% Discount S\$ :                                                                                            |          |                                 |            | 1,252.78   |
|                                                                                                                  |          |                                 |            | 5,011.12   |
| <b>LABOUR :</b>                                                                                                  |          |                                 |            |            |
| TO FOCUS HEADLAMP & CHECK HEADLAMP WIRING FUNCTION                                                               |          |                                 |            | 55.00      |
| TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS                                                              |          |                                 |            | 120.00     |
| TO CHECK COMPUTERISED WHEEL ALIGNMENT                                                                            |          |                                 |            | 120.00     |
| TO REPAIR, PANEL BEAT, ALIGN ON AFFECTED FRT BONNET, LEFT FRT DOOR & LABOUR TO REPLACE THE ABOVE MENTIONED PARTS |          |                                 |            | 700.00     |

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645  
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721  
 Tel No. : 64534177 Fax No. : 64593724  
 E-Mail : limyewboo@singnet.com.sg  
 Website : www.limyewboo.com.sg  
 Buss. Reg. No. : 200514/00L

INDIA INTERNATIONAL INSURANCE PTE LTD  
 64 CECIL STREET #05-00  
 IOB BUILDING SINGAPORE 049711

Attention : Motor Claim Department  
 Contact : 63476100 Fax No. : 62244174

## Estimate : TP20/036

Date : 22/10/2020  
 Vehicle Num. : ES 3383R  
 Make/Model : LEXUS RX 270-2012  
 Chassis/Eng# : JTJZA11A302018933/1AR0776588  
 Accident Date : 22/10/2020  
 Claim No. :  
 Reference : LYB/ES3383R/III/tp/sl  
 Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

TO PUTTY, PRIMER & SPRAY PAINT ON FRONT BUMPER, LEFT  
 FRT FENDER & TOUCH UP ON AFFECTED FRT BONNET USING 2K  
 PAINT

4801  
 700.00

Labour Total S\$ :

1,695.00

E. & O.E.

Total S\$ : 6,706.12

for LIM YEW BOO SPRAY PAINT CO.

