



MY CAR CONSULTANT PTE LTD

Reg no.: 2016058782

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408034

HP: 98888885

Estimation

Date:

24/11/2020

Vehicle:

GV657G

Make / Model:

MITSUBISHI L300

Chassis No:

No.	Description	Unit	Unit Price	Amount	
Parts Replacement:					
1	FRONT BUMPER / DR	1	\$ 828.00	\$ 828.00	640/
2	FRONT BUMPER SIDE RETAINER X N/A	2	\$ 45.00	\$ 90.00	X
3	HEADLAMP RH / DR	1	\$ 412.00	\$ 412.00	250/
4	FRONT SIGNAL LAMP RH / DR	1	\$ 258.00	\$ 258.00	126/
5	SIDE MIRROR RH X N/A	1	\$ 312.00	\$ 312.00	X
6	FRONT LOGO / APC	1	\$ 68.00	\$ 68.00	50/
7	FRONT PANEL / DD	1	\$ 698.00	\$ 698.00	/
8	FRONT CORNER PANEL RH / DD	1	\$ 198.00	\$ 198.00	/
9	FRONT DOOR RH / DD	1	\$ 1,025.00	\$ 1,025.00	851/
9	FRONT DOOR INNER TRIM BOARD RH / TAI	1	\$ 328.00	\$ 328.00	205/
10	FRONT DOOR WEATHERSTRIP X N/A	1	\$ 158.00	\$ 158.00	X
11	FRONT DOOR LOCK RH / Jammed	1	\$ 251.00	\$ 251.00	105/
12	FRONT DOOR GLASS RH X N/A	1	\$ 412.00	\$ 412.00	X
13	FRONT DOOR GLASS REGULATOR RH X N/A	1	\$ 298.00	\$ 298.00	X
14	FRONT DOOR GLASS MOTOR RH X N/A	1	\$ 598.00	\$ 598.00	X
16	FRONT DOOR PILLAR RH / DD	1	\$ 471.00	\$ 471.00	405/
17	FRONT DOOR OUTER MOULDING RH / DT	1	\$ 187.00	\$ 187.00	/
18	FRONT WINDSCREEN GLASS / DR	1	\$ 1,298.00	\$ 1,298.00	620/
19	FRONT WINDSCREEN MOULDING X N/A	1	\$ 212.00	\$ 212.00	X
20	FRONT WINDSCREEN PILLAR RH X (Ch 16) 1 DD	1	\$ 328.00	\$ 328.00	X
21	FRONT WIPER MOTOR X N/A	1	\$ 498.00	\$ 498.00	X
22	FRONT WIPER ARM X N/A	1	\$ 193.00	\$ 193.00	X
				\$ 9,121.00	
			Less 10%	\$ 912.10	
			Total	\$ 8,208.90	
S/Nett items:					
1	FRONT BUMPER CLIPS SET / APC	1	\$ 50.00	\$ 50.00	30/
2	FRONT DOOR INNER TRIM CLIP SET / APC	1	\$ 50.00	\$ 50.00	10/
				\$ 100.00	

Labour to:					
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00	30
2	TO REMOVE AND REFIT REVERSE SENSOR	1	\$ 150.00	\$ 150.00	X
3	REMOVE AND REFIX FRONT WINDSCREEN GLASS	1	\$ 150.00	\$ 150.00	120

4	REMOVE AND TRANSFER FRONT DOOR GLASS	1	\$ 200.00	\$ 200.00
5	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00
6	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
7	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,800.00	\$ 1,800.00
8	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,800.00	\$ 1,800.00
				\$ 4,530.00
			Parts Replacement Amount	\$ 8,308.90
			Total Amount for Labour	\$ 4,530.00
			Total Amount	\$ 12,838.90

50
X
30
600
1200

Stere (LKK)

WIL PL

18/3/20, 1.00pm

L/S

My AL SM

8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: