



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO20011558/AUqf3n2	
			Date: 29/03/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMS 5281T	Veh. Inspected	SME 5402K
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2003079/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	22/10/2020
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI ACCENT	c.c	1368
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	KMHCU41BTKU444993	Colour	GREY
	Odometer	44157 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	175/70 R14	BRIDGESTONE	6 mm
	L/H Front Tyre	175/70 R14	BRIDGESTONE	6 mm
	R/H Rear Tyre	175/70 R14	BRIDGESTONE	6 mm
	L/H Rear Tyre	175/70 R14	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	21/10/2020	Inspection Date	23/10/2020
	Survey held at	CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	