PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS

 WORKSHOP
 :
 UBI ROAD 1

 CONTACT NO
 :
 6366 2323

 FAX NO
 :
 6841 1183

REFERENCE : PA/OD/0782/2020/NS

DATE : 19-0ct-20 WIP : 53283

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY #07-16 AIG BUILDING SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR WANG JUNG MING

ADDRESS : BLK 59 TELOK BLANGAH HEIGHTS

#02-21

SINGAPORE 100059

 TELEPHONE
 :
 HP +65 80300650

 TYPE OF CLAIM
 :
 OWN DAMAGE CLAIM

 POLICY NO
 :
 1800024244-02

POLICY NO : 1800024244 VEHICLE NO : SLX 1792 Y

MODEL CODE : AUDI A7 SB 2.0 TFSI 4GF08

MODEL YEAR : 19/3/2018 ENGINE NO : CYP 079823

CHASSIS NO : WAUZZZ4G7JN026931

MILEAGE : -

DATE IN : -

ESTIMATED BY : JOHNNY BOO / ALLAN WU

ACCIDENT DATE : 14-Oct-20

PLACE OF ACCIDENT : NEX SHOPPING CENTRE CARPARK



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 1792 Y

S/N	NATURE OF JOBS		STIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N	\$ 360.00	
2	TO DISMANTLE AND REINSTALL REAR BUMPER. TO REPAIR RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 1,600.00	500
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER.		\$ 2,200.00	1100
4	TO RENEW RHS REAR RIM AND TYRE. TO CARRY OUT PRE AND POST WHEEL ALIGNMENT.	S/N	\$ 520.00	280
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	/
	TOTAL LABOUR CHARGES	:	\$ 4,872.00	





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 1792 Y

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS S/NETT	& PRICES REMARKS
1	REAR ALUMINIUM RIM - RH LLT		\$ 1,267.00	/
2	REAR RADIAL TYRE - RH		\$ 1,252.00	+
3	REAR BUMPER GUIDE SECTION - RH OUTER	en	\$ 53.00	+
4	SUNDRIES ?		\$ 300.00	?
	TOTAL SPARE PARTS	:	\$ 2,872.00	
	TOTAL LABOUR CHARGES	:	\$ 4,872.00	
	GRAND TOTAL	:	\$ 7,744.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

* PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

22/10/20

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Not Anthorised, 03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR,

WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO

MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO BODY REPAIR MANAGER **ALLAN WU** CLAIMS CONSULTANT