




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EROFIA MOTOR TRADING PTE LTD		Ref : CS/TP20011568/Uvf3q2		
1 KAKI BUKIT AVENUE 6 #02-62 AUTOBAY @KAKI BUKITSINGAPORE 417883		Date : 09-11-2020		
ON BEHALF OF WONG CHEN POH		Code : TP341		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	FW 3618G	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	22/10/2020	
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA RXZ	c.c	133
	Engine No.	HIDDEN	Year of Reg.	2003
	Chassis No.	PMY5PV10000002822	Colour	YELLOW
	Odometer	37484	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	2.75-18	METZELER	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	90-90-18	MICHELIN	6 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/09/2020	Inspection Date	22/10/2020
	Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	