

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail : xinyaauto@singnet.com.sg

Tel: 6270 3481 Fax: 6278 7522

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date : 26/10/2020

Address : LIM POW HENG
BLK 430 TAMPINES STREET.41
08-509
SINGAPORE 520430

Reference : TP 1259/10/2020
Vehicle No : SLP 5266R
Make/Model : TOYOTA ALTIS
Insurance Co. : NTUC

RE : QUOTATION TO SLP 5266R FOR THIRD PARTY CLAIMS.

<u>PARTS REQUIRED</u>		<u>QTY</u>		<u>AMT \$</u>
1)	REAR LEFT DOOR	1	\$	1,248.90 <i>bt ✓</i>
2)	DOOR HINGES	2	\$	170.40 <i>Rp ✓</i>
3)	TOP CHROME	1	\$	128.60 <i>de ✓</i>
4)	DOOR WEATHERSTRIP	1	\$	180.70 <i>re ✓</i>
5)	DOOR GLASS REGULATOR	1	\$	540.00 <i>? photo</i>
LIST PRICE TOTAL			\$	2,268.60
LESS DISCOUNT 25%			\$	567.15
LIST PRICE TOTAL AFTER LESS			\$	1,701.45
NETT PRICE TOTAL				\$0.00
TOTAL PARTS COST				\$1,701.45

LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE REAR LH DOOR .DOOR HINGES DOOR WEATHERSTRIPE.	\$	400.00 <i>200</i> (2 DAYS)
2)	TO PUTTY & SPRAY PAINT REAR LH DOOR INNER & OUTER.	\$	400.00 <i>250.</i> (2 PANELS)
3)	TO REMOVE OLD DOOR MECHANISM PARTS & DOOR GLASS TO NEW DOOR	\$	180.00 <i>60</i>
4)	TO CHECK AND RECTIFY REAR LH DOOR WIRING.	\$	80.00 <i>x</i>
LABOUR TOTAL			\$ 980.00

Tanphk 97455749
-wp 28/10/20 @ 1045
Lump sum, Resurvey after repair
02 days
Tanphk @ Khairudin