

COMFORTDELGRO PTE LTD
REPAIR ESTIMATE*

VEHICLE NO SHB6622K
 MAKE :
 MODEL IONIQ G2

26/10/20
 CHIANG/AIG

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER X R		\$459.40
1	REAR BUMPER SIDE BRACKET RH /LH X NM		\$111.60
10	REAR BUMPER CLIPS X NM		\$22.00
1	REAR BUMPER REINFORCEMENT ? X NM		\$294.80
1	REAR BUMPER REINFORCEMENT BRACKET X NM		\$276.20
1	REAR BUMPER LOWER MOULDING / (UT (low))		\$155.00
1	REAR BUMPER FOG LAMP ? X NM		\$201.50
1	REAR BUMPER CENTRE MOULDING / (UT		\$451.25
1	REAR BUMPER REFLECTOR RH/ LH X NM		\$63.80
1	REAR FLOOR UNDER X NM		\$225.00
1	SMART KEY ANTENNA ? X NM		\$665.40
1	REAR BUMPER TOW COVER X NM		\$98.80
SUB TOTAL			\$3,024.75
20.00%			\$604.95
DISCOUNTED TOTAL			\$2,419.80
1	REAR NUMBER PLATE/W HOLDER - BR		\$50.00
1	REAR REVERSE SENSOR - BR		\$180.00
			\$230.00
Labour Charge			
Panel Beating			\$650.00
Spray Painting Charge			\$400.00
Check wiring			\$60.00
Tuff Kote			\$60.00
Remove/refix Reverse sensor			\$60.00
TOTAL LABOUR			\$1,230.00
ESTIMATE TOTAL			\$4,256.68

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Sten (LKK) w PL
 26/10/20, 11.30a
 2 dy
 P/P
 My BL sy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company