



JKS MOTOR WORKS PTE LTD

8 KAKI BUKIT AVENUE 4, #03-45, Premier @ Kaki Bukit, Singapore, 415875

Company Reg No. : 201407714K

HP NO. 8811-9996

EMAIL : admin@jksmotorworks.com.sg

Eno Qiang
82880282
10/12/2020

4 Days.

Impress Repair
After repair photos

Motor Claims Department

INDIA INTERNATIONAL INSURANCE

64 Cecil Street, #05 - 10B Building

SINGAPORE 049711

REF NO :

VEH NO : SH7311P; ON 22 OCT 2020 @ JUNCTION OF

MARYMOUNT LANE & UPP THOMSON RD

@ 12:25 PM

Date:

JKS Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval of the Insurance Company
Acknowledged by Repairer

QUOTATION

QUOTE NO : JKSQUOTE129

DATE : 8-Dec-20

VEHICLE NO : SMF7111G

MAKE/MODEL : HONDA VEZEL HYB

CHASSIS : LEB5916948

ENGINE NO : RU31216938

REG. DATE : 20-Jan-17

CAPACITY : 1.5 cc

ESTIMATE FOR : SMF7111G HONDA VEZEL HYBRID

Description	Qty	UOM	Repairer's Estimate	Revised Amount (Less 20%)
SPARE PARTS				
1 DOOR FRONT LH <i>✓ 4 BUC</i>	1	PC	930.60 ✓	744.48
2 DOOR REAR LH <i>✓ 4 BUC</i>	1	PC	900.00 ✓	720.00
3 DOOR LOCK LH FR & RR <i>X</i>	2	PCS	520.00	416.00
4 DOOR RUBBER LH FR & RR <i>X</i>	2	PCS	120.00	96.00
5 DOOR RUBBER LH FR & RR <i>X</i>	2	PCS	80.00	64.00
6 DOOR RUBBER BELOW LH FR & RR <i>X</i>	2	PCS	80.00	64.00
7 DOOR STICKER LH <i>X 1pc</i>	1	PC	30.00	24.00
8 DOOR WEATHERSTRIP LH FR & RR <i>X</i>	2	PCS	320.00	256.00
9 DOOR MOULDING LH FR & RR <i>X</i>	2	PCS	60.00	48.00
10 DOOR TAPE LH FR & RR <i>✓ 1pc</i>	2	PCS	40.00 ✓	32.00
NETT PRICE			1870.6	1496.48
11 SOUND PROOF DOOR LH FR & RR <i>X NN</i>	1	SRV	850.00	850.00
LABOUR				
12 LABOUR CHARGE TO REPAIR & REBUILD INCLUDING CUT & WELD WHERE NECESSARY; REMOVE & REPACE REAR DAMAGE PARTS AS LISTED ABOVE	1	SRV	1,000.00	1,000.00 <i>400</i>
13 TO SPRAY PAINT ON REAR PORTION AFFECTED AREAS	1	SRV	800.00	800.00 <i>500</i>
14 MATT BLACK STICKER <i>1pc</i> X NN	1	SRV	800.00	800.00 <i>X</i>
15 TO REMOVE AND REINSTALL LEFT FR & RR DOOR GLASS TO FACILITATE REPAIR	1	SRV	360.00	360.00 <i>300</i>
16 SOUND PROOF DOORS LH FR & RR	1	SRV	600.00	600.00 <i>1000</i>
			2496.48	1000

-20%: 2000