

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: PY1-ylv-Ins-H47-112794-20(et)

Date: 21st Jan 2021

Our Ref: CS1/LAW20011657/Avf3e2

## M/s Vision Law LLC

133 New Bridge Road #18-01/02 Chinatown Point Singapore 059413

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJR 7374L INSURED VEHICLE: SKL 2385H

**ACCIDENT DATE: 29/01/2020** 

We thank you for your instruction on 26/10/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJR 7374L from M/s Pal's Appraiser Pte Ltd.
- b) Survey report by L.B.S. Auto Consultants Pte Ltd with colour photographs.
- c) Final Repair Bill of SJR 7374L from M/s Hua Meng Spray Painting Workshop.
- d) Singapore Accident Statement of Vehicles SJR 7374L and SKL 2385H.
- e) Colour damaged vehicle photographs of SJR 7374L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SJR 7374L

Make & Model : Hyundai HD Avante 1.6A Chassis Number : KMHDU41BR9U774252

Year of Registration : 2009 Engine Capacity : 1591 cc

- 2. We recommend that the repairs of the entire damage require about \_\_\_\_\_\_ 5 (Five) \_\_\_\_\_ working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.