

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref : CS/SMO2001	1665/Utf3q2
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623			Date : 10-11-2020 Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLD 7012G	Veh. Inspected	SLN 7070K
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2003108/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	27/10/2020
2. Vehicle Particulars & Condition				
	Make & Model	KIA SORENTO (A)	c.c	2199
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	KNAPH81BMH5318519	Colour	BROWN
	Odometer	75943	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R19	GOODYEAR	6 mm
	L/H Front Tyre	235/55 R19	GOODYEAR	6 mm
	R/H Rear Tyre	235/55 R19	GOODYEAR	6 mm
	L/H Rear Tyre	235/55 R19	GOODYEAR	6 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	23/10/2020	Inspection Date	28/10/2020
	Survey held at TEAMWORK GARAGE PTE LTD			
		53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days			