



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0801/2020/NS
DATE : 26-Oct-20
WIP : 54412

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR LIM WEISHENG, VINCENT(LIN WEISHENG)
ADDRESS	:	BLK 70C TELOK BLANGAH HEIGHTS #06-533 SINGAPORE 103070
TELEPHONE	:	HP +65 87530058
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2070135123
VEHICLE NO	:	SBN 7318 R
MODEL CODE	:	AUDI Q3 SPORTSBACK 1.4 TFS
MODEL YEAR	:	18/9/2020
ENGINE NO	:	CZD C04066
CHASSIS NO	:	WAUZZZF32M1000646
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	21-Oct-20
PLACE OF ACCIDENT	:	8 LIANG SEAH ST S(189029)



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SBN 7318 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
TO REMOVE AND REINSTALL REAR PARKING AID AND			
1	REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	X.
TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.			
2		S/N \$ 280.00	✓
TO RENEW RHS REAR 1/4 GLASS TO FACILITATE FENDER RENEWAL.			
3		S/N \$ 300.00	✓
TO INSTALL SOLAR FILM FOR RHS REAR 1/4 GLASS.			
4		S/N \$ 400.00	X.
TO CARRY OUT WATER SEEPAGE TEST FOR RHS REAR 1/4 GLASS.			
5		S/N \$ 200.00 150	
SUB TOTAL LABOUR CHARGES		: \$ 1,540.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SBN 7318 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,400.00 ✓	
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00 ✓	
8	TO DISMANTLE REAR BUMPER, REAR LID AND RHS REAR DOOR. TO RENEW RHS REAR DOOR. CUT OUT AND WELD RHS REAR FENDER AND REAR OUTER END PANELLING. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓	\$ 9,600.00 ✓ <i>3500 (without end panel)</i>	
9	TO RESPRAY RHS REAR FENDER, RHS REAR DOOR, DOOR COVER, BOTH REAR WHEEL ARCH TRIMS, DOOR ENTRANCES, RHS SILL PANEL, ROOF CHANNEL. DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS. <i>Handle</i> ✓	<i>3175</i> \$ 5,750.00 ✓ <i>4.5 x 550 = 2475</i> <i>Wheel covers x 2 = 200 x 2 = 400</i> <i>Door Cover = 200</i> <i>Handle = 100</i> <i>3175</i>	
10	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00 X	
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 20,162.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBN 7318 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 REAR FENDER - RH <i>Dented</i>		\$ 3,431.00	✓
2 REAR CROSS PANEL ?		\$ 417.00	?
3 SIDE WINDOW - RH <i>new</i>		\$ 607.00	✓
4 REAR BUMPER GUIDE SECTION - RH		\$ 63.00	✓
5 REAR WHEEL HOUSING LINER - RH		\$ 239.00	✓
6 WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 100.00	✓
7 REAR DOOR - RH <i>Dented</i>		\$ 2,553.00	✓
8 REAR OUTER DOOR SEAL <i>new</i>	NEC	\$ 134.00	✓
9 REAR DOOR CATCH ?		\$ 119.00	?
10 STILL PANEL SEAL - RH ?		\$ 134.00	?
11 REAR DOOR COVER - RH <i>new</i>		\$ 345.00	✓
12 REAR WHEEL COVER - LH / RH <i>new</i>	2	\$ 1,060.00	✓
13 REAR ALUMINIUM RIM - RH <i>new</i>		\$ 756.00	✓
14 1/4 GLASS SEALANT	S/N	\$ 100.00	✓
15 METAL FILLER POWDER	S/N	\$ 280.00	✓
16 STONE CHIP	S/N	\$ 180.00	✓
17 CAVITY WAX	S/N	\$ 140.00	✓
18 ACRYLIC SEALANT	S/N	\$ 180.00	✓
19 SUNDRIES ?		\$ 300.00	?
TOTAL SPARE PARTS	:	\$ 11,138.00	
TOTAL LABOUR CHARGES	:	\$ 20,162.00	
GRAND TOTAL	:	\$ 31,300.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adrian
27/10/20.

Not Authorised, 13 Days (without end panel)

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT