

NGIAK MOTOR WORKS

MAILING ADDRESS: BLK 6, GHIM MOH ROAD #10-194

SINGAPORE 270006

H/P: 9850 2253

Reg. No. 207300/00C

Not Authorized
61 Day @ 1550/hr
Per day After Paint
4 days

Date: 26th Oct 2020

Quotation: SGO 7950 P Honda Insight

S\$

1 Pc. Front bumper 925.10 ✓

1 Pc. Front bumper grille garnish 438.20 cm 589.60 ✓

2 Pcs Front bumper side retainer @ 34.90 ea 69.80 X

1 Set Front bumper clips ea 45.00 ✓

1 Pc. Front no. plate garnish 60.50 ✓

1, 690.00

Less 20% 338.00

1, 352.00

Nett Items: -

1 Set Front no. plate & casing 50.00 45ea

Labour: -

① To check & do computerised wheel alignment. } ea 100.00 X

② Panel beating 320.00 28.0

③ Spray painting 500.00 45ea

2, 322.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: