

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	NTUC INCOME IN:	SURANCE CO-OPERATIVE LTD		Ref:	CS/INC20011718/Gqf3e2	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE		Date:	08/03/2021	
	ATTN: DAVID PHU	A		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBF 7331T	Veh. Inspected		SLB 5956G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1107715-002	Excess (\$)		0.00	
	Assign From	HAZALYSA BTE IBRAHIM	Assign Date		28/10/2020	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA CITY 1.5	c.c		1497	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	MRHGM6660GP000567	Colour		BLUE	
	Odometer	37736 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/55 R16	YOKOHAMA		6 mm	
	L/H Front Tyre	185/55 R16	YOKOHAMA		6 mm	
	R/H Rear Tyre	185/55 R16	YOKOHAMA		6 mm	
	L/H Rear Tyre	185/55 R16	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	24/10/2020	Inspection Dat	е	28/10/2020	
	Survey held at	DETAIL LAB				
		BLK 8 KAKI BUKIT AVE 4 #02-03/04 PREMIER @ KB SINGAPORE 415875				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					