

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 18 Nov 2020

## **Preliminary Advice**

|                    |                                                                                                       |                         |              |
|--------------------|-------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SJF384S                                                                                             |                         |              |
| TP Vehicle No      | : SHC4754X                                                                                            | Accident Date           | : 27/10/2020 |
| Make               | : TOYOTA PRIUS                                                                                        | Assignment Date         | : 28/10/2020 |
| Date of Inspection | : 28/10/2020                                                                                          | Est. Duration of Repair | : 2          |
| Inspection At      | : SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS)<br>60 WOODLANDS INDUSTRIAL PARK E4<br>SINGAPORE 757705 |                         |              |

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 4,100.00 |
| Revised Amount              | :S\$ | 520.00   |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 520.00   |

|                 |      |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

### **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :The above survey was conducted without "prejudice" basis.