

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

submit to ins

Not Authorized
New
1/5 to 11,300/
12 days.

VEHICLE NO: SJK 1513P

QTY	PARTICULAR			
1 PCS	REAR WINDSCREEN	Shattered	1148.10	\$1,288.50 /
1 PCS	REAR WINDSCREEN MOULDING	neu		\$128.70 /
1 PCS	TAILGATE	Body ID	1248.10	\$1,866.10 /
1 PCS	TAILGATE INNER LOCK	20/3m		\$388.80 /
1 PCS	TAILGATE REAR LOGO	neu		\$68.10 /
1 PCS	TAILGATE 'WISH' EMBLEM	N/E		\$60.50 X
1 PCS	TAILGATE INNER TRIM BOARD	De/cra	485.10	\$645.10 /
1 SET	TAILGATE INNER TRIM BOARD CLIPS	neu		\$50.00 /
1 PCS	TAILGATE WEATHERSTRIP	YWI	281.50	\$299.50 /
1 PCS	TAILGATE OUTER CHROME MOULDING	CNE		\$388.20 /
2 PCS	TAILGATE DAMPERS @\$350.00	1 1		\$700.00 X
1 PCS	TAILGATE INNER HOLDER GARNISH	1 1		\$45.00 X
1 PCS	REAR BUMPER	D/S	492.30	\$665.30 /
2 PCS	REAR BUMPER REFLECTORS @\$105.00	N/S CNE	68.50	\$210.00 1PC
2 PCS	REAR BUMPER SIDE HOLDERS @\$68.50	N/S Surf		\$137.00 1PC
1 SET	REAR BUMPER CLIPS	neu		\$50.00 /
2 PCS	REAR BUMPER DAMPERS @\$55.60	S/L		\$111.20 X
1 PCS	REAR END PANEL	Body ID	645.20	\$699.10 /
1 PCS	REAR END PANEL LOWER MEMEBR	Body ID		\$211.50 /
1 PCS	REAR END PANEL TOP GARNISH	TWI	265.30	\$288.60 /
2 PCS	TAILLAMPS @\$458.10	CNE	408.10 x 2 = 816.20	\$916.20 /
2 PCS	TAILLAMP HOUSING PANELS @\$455.10	N/S ID	399.50	\$910.20 1PC
1 PCS	REAR FLOOR PANEL	Crumpled/3uc	1099.50	\$1,120.10 /
1 PCS	REAR FLOOR PANEL TOP BOARD	1 1		\$588.20 X
2 PCS	REAR FENDERS @\$977.10	R		\$1,954.20 X
2 PCS	REAR FENDER INNER TRIM BOARDS @\$605.10	N/S Torn o/san		\$1,210.20 1PC
1 SET	REAR FENDER INNER TRIM BOARD CLIPS	1 1		\$50.00 X
1 PCS	REAR EXHAUST	1 1		\$788.50 X
2 PCS	REAR EXHAUST MOUNTINGS @\$65.00	1 1		\$130.00 X
1 PCS	REAR EXHAUST HEAT SHIELD	1 1		\$211.10 X
1 PCS	REAR SPARE TYRE BRACKET & CARRIAGE	1 1		\$450.50 X
1 PCS	REAR AIR VENT	1 1		\$121.00 X
1 PCS	BONNET	R		\$678.10 X
1 PCS	BONNET INSULATOR	1 1		\$211.50 X
1 SET	BONNET INSULATOR CLIPS	1 1		\$50.00 X
1 PCS	BONNET LOCK	1 1		\$145.50 X
1 PCS	BONNET OUTER CHROME MOULDING	1 1		\$155.30 X
2 PCS	HEADLAMPS @\$689.10	CNE		\$1,378.20 /
1 PCS	FRONT BUMPER	D/S/Torn	645.10	\$830.00 /
1 PCS	FRONT BUMPER REINFORCEMENT	Surf		\$266.20 /
1 PCS	FRONT BUMPER SPONGE	Torn		\$166.50 /
2 PCS	FRONT BUMPER SIDE HOLDERS @\$65.50	1 1		\$131.00 X
1 SET	FRONT BUMPER CLIPS	neu		\$50.00 /
2 PCS	FRONT BUMPER FOG LAMP COVERS @\$68.00	1 1		\$136.00 X
1 PCS	FRONT BUMPER CENTRE GRILLE	Torn	148.20	\$188.20 /
1 PCS	FRONT GRILLE	CNE		\$166.60 /

(25%)

1 PCS	FRONT BRACE PANEL	Yw1	\$121.50	✓
1 PCS	FRONT SUPPORT PANEL	R	\$688.10	X
1 PCS	AIR CON CONDENSER	Beaf / Pun	\$1,213.10	✓
1 PCS	AIR CON SUCTION HOSE	11	\$395.50	X
1 PCS	AIR CON DISCHARGE HOSE	11	\$388.10	X
1 PCS	RADIATOR	holder crs 1665.10	\$1,866.50	✓
1 PCS	RADIATOR FAN MOTOR	11	\$450.50	X
1 PCS	RADIATOR FAN BLADE	11	\$150.40	X
1 PCS	RADIATOR FAN COWLING	11	\$209.10	X
2 PCS	HORN UNITS @\$105.00	11	\$210.00	X
2 PCS	FRONT FENDERS @\$650.10	11	\$1,300.20	X
2 PCS	FRONT FENDER INNERSHIELDS @\$195.10	11	\$390.20	X
			\$28,687.70	
	S.NETT			
1 PCS Set	REAR BUMPER REVERSE SENSOR	shorted	\$280.00	200
1 PCS	REAR END PANEL SEALANT	neu	\$50.00	✓
1 PCS	REAR FLOOR PANEL INSULATOR	neu	\$200.00	120
1 PCS	REAR WINDSCREEN SEALANT	neu	\$50.00	40
1 SET	REAR LICENCE PLATE W/HOLDER	Beaf	\$50.00	40
1 SET	FRONT LICENCE PLATE W/HOLDER	Beaf	\$50.00	40
1 BOL	RADIATOR COOLANT	11	\$50.00	X
	LABOUR CHARGES:			
	TO CHECK WIRING		\$80.00	30
	TO DISMANTLE & REPLACING REAR REVERSE SENSOR		\$80.00	50
	TO DISMANTLE & REFIX REAR WINDSCREEN		\$150.00	120
	TO TRANSFER TAILGATE MECHANISM		\$100.00	60
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY		\$150.00	80
	TO DISMANTLE & REFIX REAR EXHAUST	11	\$100.00	X
	TO DISMANTLE & REFIX PETROL TANK	11	\$100.00	X
	TO MOUNT VEHICLE ON CAR O-LINER	11	\$380.00	X
	TO REFILL AIRCON GAS		\$150.00	100
	TO SPRAY RUST PROOFING		\$200.00	100
	LABOUR FOR PANEL BEATING & REPLACING PARTS		\$2,800.00	1600
	TO PUTTY & SPRAY PAINTING		\$2,500.00	1800
	TOTAL		\$36,207.70	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3940

14728.7
2570
11046.52
15475.57
12381