



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:WINNIE			Ref: CC4/ASM20011760/Apa3q2 Date: 14/11/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLR 5529Y	Veh. Inspected	SKF 8198Z	
Policy No.	P2389165	Coverage (\$)	0.00	
Claim No.	S0M02W3V	Excess (\$)	0.00	
Assign From		Assign Date	28/10/2020	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI VELOSTER	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	KMHTC61DVCU081761	Colour	BROWN	
Odometer	189551 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	HIFLY	6 mm	
L/H Front Tyre	225/40 R18	HIFLY	6 mm	
R/H Rear Tyre	225/40 R18	HIFLY	6 mm	
L/H Rear Tyre	225/40 R18	HIFLY	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/10/2020	Inspection Date	28/10/2020	
Survey held at	DYNAMIC AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4 #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	