



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref : 5081946845SG

Date: 30th Nov 2020

Our Ref : CS/AIG20011771/Gsd3e2

M/s Aig Asia Pacific Insurance Pte Ltd

78 Shenton Way #09-16

Aig Building

Singapore 079120

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMV 835M
ACCIDENT ON 26/10/2020**

Instruction was received to inspect the vehicle Reg. No. SMC 835M. The inspection was conducted on 28/10/2020 at the premises of M/s BW Workshop Services Pte Ltd, 291 Kaki Bukit Avenue 1, Shun Li Industrial Park, Singapore 416080.

The following vehicle information was recorded:

Registration Number	: SMV 835M
Make/Model	: Toyota Voxy Hybrid 7-Seater 1.8V CVT
Year of Registration	: 2020
Body Colour	: Black
Chassis Number	: ZWR800403150
Engine Capacity	: 1797 cc
Speedometer Reading	: -

The vehicle sustained damages at the front portion and undercarriage. The Estimated repair cost of such vehicle is S\$62,557.30 (Sin Dollars: Sixty-Two Thousand Five Hundred Fifty-Seven and Thirty Cents only.) (Exclude check items S\$51,473.30Nett) (Details see photographs enclosed)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **"Total Loss"**.

(a) If the vehicle to be "Total Loss"

Market Value

S\$ 120,000.00

Less: LTA Reimbursement Value (RV)

(S\$ 65,753.00)

S\$ 57,247.00

Less: Excess

(S\$ 600.00)

Nett Liability

S\$ 53,647.00

(b) If the vehicle to be "Repair"

Repair Cost (Est)

S\$ 62,557.30

(Exclude check items S\$51,473.30Nett)

Less: Excess

(S\$ 600.00)

Nett Liability

S\$ 61,957.30

(a) - (b) =

(S\$ 8,310.30)

=====

The amount of estimated saving of S\$8,310.30 if the vehicle to be written off as **"Total Loss"** instead of to be repair.

Vehicle Inspected By:

XING GUO QIANG
M.MATAI, AMSAE-A
Automotive Assessor

K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.