

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 29 Oct 2020

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|--------------|
| Vehicle No | : SMV835M | Accident Date | : 26/10/2020 |
| Make | : TOYOTA VOXY HYBRID | Policy No. | : 2070134931 |
| Assignment Date | : 29/10/2020 | Excess | : S\$0.00 |
| Date of Inspection | : 29/10/2020 | Est. Duration of Repair | : |
| Inspection At | : BW Workshop Services Pte Ltd (HQ) 291 Kaki Bukit Avenue 1, Shun Li Industrial Park Singapore 416080 | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|--------------------|
| Repairer's Estimate (Gross) | :S\$ | Estimate not ready |
| Revised Amount | :S\$ | Estimate not ready |
| Check Items (Estimated) | :S\$ | Estimate not ready |
| Total | :S\$ | Estimate not ready |
| Lump Sum Repair | :S\$ | |

Total Loss Consideration

| | | |
|--------------------|------|------------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 120,000.00 |
| COE / PARF Rebate | :S\$ | 65,753.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 54,247.00 |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :