

(08/11/13) wof

ASS. REC. BY: marcus

REF:

CC6/CT/20011779/4ka3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

JKS 8925

at Workshop m/s

7 Khe

of

Insured:

YN 7127C

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

RM 26

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

11 days

Res.: Yes or No

Lrm Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Sum insured 26

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

JKS 8925

Yr Regn:

1, 08

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Nissan grand Living c.c

1798

Colour

Blu

A/C: Insured / Std / NI / NA

Sp. Reading

426279

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

PN8BCAL10TCA20371

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake: In Order / Jammed / Leaked / Burnt or

Modi: Nil / 3/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/45R17

BS / DUN / EXNOVA / GYFS / EIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6 mm

Rear

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

27/10/20

D.O.I.

29/10/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Fl.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/11/20 \$2600 confirmed with AH ha;

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$

Uth Khon Chon

not Authorised

2/10/20

L/S #8600

The Motor Claims Dept.

29/10/20

11 days

T K LEE AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

YN7127C

ESTIMATE

DATE : 28/10/2020

VEHICLE NO : JKS8925

MAKE/MODEL : NISSAN LIVINA

ACC DATE : 27/10/2020

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
NETT PRICE			
1	1 REAR WINDSCREEN GLASS <i>shotted</i>	\$ 1,091.00	\$ 1,091.00 ✓
2	1 REAR TAILGATE <i>300500</i>	\$ 2,124.80	\$ 2,124.80 ✓
3	2 REAR TAILGATE HINGE RH / LH <i>17</i>	\$ 108.90	\$ 217.80 X
4	2 REAR TAILGATE DAMPER RH / LH <i>17</i>	\$ 279.30	\$ 558.60 X
5	1 REAR TAILGATE RUBBER <i>1m</i>	\$ 239.90	\$ 239.90 ✓
6	1 REAR TAILGATE LOCK <i>JM</i>	\$ 276.30	\$ 276.30 ✓
7	1 REAR TAILGATE LOCK CATCH <i>17</i>	\$ 46.10	\$ 46.10 X
8	1 REAR TAILGATE WIPER BLADE <i>MJS</i>	\$ 36.20	\$ 36.20 ✓
9	1 REAR TAILGATE WIPER ARM <i>CM</i>	\$ 85.20	\$ 85.20 ✓
10	1 REAR TAILGATE WIPER MOTOR <i>surf/JM</i>	\$ 471.30	\$ 471.30 ✓
11	1 REAR TAILGATE WIPER MOTOR GARNISH <i>17</i>	\$ 128.60	\$ 128.60 X
12	1 REAR TAILGATE OUTER HANDLE <i>17</i>	\$ 115.60	\$ 115.60 X
13	1 REAR TAILGATE EMBLEM LOGO <i>17</i>	\$ 65.00	\$ 65.00 ✓
14	1 REAR TAILGATE EMBLEM 'GRAND LIVINA' <i>17</i>	\$ 85.20	\$ 85.20 ✓
15	1 REAR TAILGATE EMBLEM '1.8' <i>17</i>	\$ 75.10	\$ 75.10 ✓
16	1 REAR TAILGATE TOP SPOILER <i>CM</i>	\$ 588.00	\$ 588.00 ✓
17	2 REAR TAILLAMP RH / LH <i>370</i>	\$ 415.60	\$ 831.20 ✓
18	2 REAR TAILLAMP PANEL HOUSING RH / LH <i>R</i>	\$ 291.50	\$ 583.00 X
19	1 REAR BUMPER <i>DIS</i>	\$ 755.50	\$ 755.50 ✓
20	2 REAR BUMPER NUMBER PLATE LAMP <i>CM</i>	\$ 48.60	\$ 97.20 ✓
21	1 REAR BUMPER NUMBER PLATE BRACKET <i>surf</i>	\$ 108.50	\$ 108.50 ✓
22	2 REAR BUMPER SIDE RETAINER RH / LH <i>17/300</i>	\$ 54.10	\$ 108.20 ✓
23	1 REAR END PANEL <i>21600</i>	\$ 518.60	\$ 518.60 ✓
24	1 REAR END PANEL GARNISH <i>17</i>	\$ 173.10	\$ 173.10 ✓
25	2 REAR FENDER INNER TRIM RH / LH <i>8VC</i>	\$ 369.80	\$ 739.60 X
26	1 FRONT BONNET <i>22/300</i>	\$ 1,054.30	\$ 1,054.30 ✓
27	2 FRONT BONNET HINGE RH / LH <i>17</i>	\$ 56.40	\$ 112.80 X

87278

T K LEE AUTOMOTIVE PTE. LTD.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
NETT PRICE			
28	2 FRONT BONNET RUBBER RH / LH <i>nr</i>	\$ 54.10	\$ 108.20 <i>X</i>
29	1 FRONT BONNET INSULATOR <i>nr</i>	\$ 138.20	\$ 138.20 <i>X</i>
30	1 FRONT BONNET LOCK <i>nr</i>	\$ 68.30	\$ 68.30 <i>✓</i>
31	2 FRONT HEADLAMP RH / LH <i>one</i>	\$ 691.80	\$ 1,383.60 <i>✓</i>
32	1 FRONT GRILLE <i>one</i>	\$ 665.60	\$ 665.60 <i>✓</i>
33	1 FRONT GRILLE EMBLEM LOGO <i>nr</i>	\$ 66.10	\$ 66.10 <i>✓</i>
34	1 FRONT BUMPER <i>nr/10.1</i>	\$ 758.00	\$ 758.00 <i>✓</i>
35	1 FRONT BUMPER TOW COVER <i>nr</i>	\$ 29.80	\$ 29.80 <i>X</i>
36	1 FRONT BUMPER FOG LAMP RH <i>nr</i>	\$ 320.70	\$ 320.70 <i>X</i>
37	1 FRONT BUMPER REINFORCEMENT <i>TD</i>	\$ 705.80	\$ 705.80 <i>✓</i>
38	2 FRONT BUMPER SIDE RETAINER RH / LH <i>o/s bent</i>	\$ 45.20	\$ 90.40 <i>1 pc</i>
39	1 FRONT SUPPORT PANEL <i>surf/Buc</i>	\$ 753.60	\$ 753.60 <i>✓</i>
40	1 FRONT BRACE PANEL <i>surf</i>	\$ 101.30	\$ 101.30 <i>✓</i>
41	1 AIR CON CONDENSER <i>pur</i>	\$ 625.60	\$ 625.60 <i>✓</i>
42	1 AIR CON DISCHARGE PIPE <i>nr</i>	\$ 192.80	\$ 192.80 <i>X</i>
43	1 AIR CON SUCTION PIPE <i>nr</i>	\$ 208.60	\$ 208.60 <i>X</i>
44	1 RADIATOR <i>holder one</i>	\$ 724.20	\$ 724.20 <i>✓</i>
45	1 RADIATOR SPARE TANK <i>nr</i>	\$ 143.20	\$ 143.20 <i>X</i>
46	1 RADIATOR FAN COWLING <i>nr</i>	\$ 208.20	\$ 208.20 <i>X</i>
47	1 RADIATOR FAN BLADE <i>nr</i>	\$ 128.60	\$ 128.60 <i>X</i>
48	1 RADIATOR FAN MOTOR <i>nr</i>	\$ 495.00	\$ 495.00 <i>X</i>
49	1 AIR CLEANER BOX INAKE AIR DUCT <i>one</i>	\$ 119.00	\$ 119.00 <i>✓</i>
			\$ 19,321.50
LESS 10%			\$ 1,932.15
TOTAL			\$ 17,389.35

SPECIAL NETTS ITEM					
1	1 REAR WINDSCREEN SPONGE TAPE <i>nr</i>	\$	20.00	\$	20.00 <i>✓</i>
2	1 (SET) REAR WINDSCREEN SEALANT <i>nr</i>	\$	80.00	\$	80.00 <i>40</i>
3	1 REAR WUBDSCEEB <i>Solar film nr</i>	\$	220.00	\$	220.00 <i>120</i>
4	1 REAR NUMBER PLATE <i>surf</i>	\$	35.00	\$	35.00 <i>14</i>
5	1 (SET) REAR BUMPER REVERSE SENSOR <i>shard</i>	\$	280.00	\$	280.00 <i>200</i>
6	1 (SET) REAR BUMPER CLIPS <i>nr</i>	\$	35.00	\$	35.00 <i>✓</i>
7	1 (SET) FRONT BONNET INSULATOR CLIP <i>nr</i>	\$	45.00	\$	45.00 <i>X</i>
8	1 FRONT NUMBER PLATE <i>sep</i>	\$	25.00	\$	25.00 <i>14</i>
9	1 (SET) FRONT BUMPER CLIP <i>nr</i>	\$	45.00	\$	45.00 <i>✓</i>
10	1 AIR CON COIL <i>nr</i>	\$	45.00	\$	45.00 <i>X</i>
11	1 AIR CON AUTO FAN <i>nr</i>	\$	400.00	\$	400.00 <i>X</i>
12	1 (LIT) RADIATOR COOLANT <i>nr</i>	\$	25.00	\$	25.00 <i>X</i>
TOTAL				\$	1,255.00

1988

LABOUR CHARGES :

1	TO KNOCK OUT DENT, CUT/WELD REAR PANEL, FRONT SUPPORT PANEL, REPAIR REAR FENDER AND REPLACE ACCIDENT PARTS	\$	1,500.00	1200
2	TO SPRAY PAINTING ON ACCIDENT PARTS	\$	1,600.00	1500
3	TO CHECK FRONT AND REAR WIRING	\$	60.00	30
4	TO REMOVE, REPLACE CONDENSER AND REFILL GAS	\$	100.00	L
5	TO REMOVE, REPLACE REAR WINDSCREEN	\$	120.00	✓
6	TO TRANSFER REAR TAILGATE PARTS	\$	100.00	60
7	TO REMOVE, REFIX CUSHION AND INNER TRIM	\$	120.00	80
8	TO REMOVE, REPLACE REVERSE SENSOR	\$	80.00	50
9	TO TUFF - KOTE	\$	150.00	100
TOTAL:		\$	3,830.00	

3240

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 22,474.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: