



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL
64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV No. AC2007468
INV Date 09/11/2020
Reference CS3/III20011789/Gqf3e2
Code III2



PROFESSIONAL SERVICE FEE

Vehicle No. SLE 5482R
Insured Veh. PC 1632P
Claim No. MFL2020D0002221
Policy No. D20MFL0003256
Accident Date 26/10/2020
Inspection Date 29/10/2020

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 29.10.2020 06.30pm	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM