

LKK Auto Consultants Pte Ltd

Page No.:1 of 2

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDQ 38E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT	DENTED	2,212.50	1,712.85
1	REAR BOOT RUBBER STOPPER	NOT NECESSARY	121.60	-
1	REAR CENTRE CHROME GARNISH	NOT NECESSARY	968.80	-
1	REAR BOOT EMBLEM	NOT NECESSARY	268.40	-
1	REAR BUMPER	DENTED	973.50	876.15
1	REAR BUMPER REFLECTOR LEFT	NOT NECESSARY	198.50	-
1	REAR BUMPER REFLECTOR RIGHT	NOT NECESSARY	198.50	-
1	REAR BOOT EMBLEM 'HYBRID LOGO'	NECESSARY	148.70	95.80
1	REAR INNER PANEL	TO REPAIR SEE LABOUR	168.70	-
1	REAR FENDER LAMP WITH CHROME LEFT	NOT NECESSARY	991.60	-
1	REAR BOOT LOCK	BENT	668.90	368.00
1	REAR BOOT DAMPER	NOT NECESSARY	310.40	-
1	DOOR LOCK HINGE	NOT NECESSARY	128.90	-
1	REAR END PANEL	DENTED	775.80	564.20
	LESS 20% DISCOUNT		-1,626.96	-
	LESS 25% DISCOUNT		-	-904.25
			6,507.84	2,712.75
	<u>LABOUR</u>			
	TO FIX & DISMANTLE AND REMOVE DAMAGED REAR PORTION; AFFECTED DAMAGED PORTION. INCLUSIVE OF THE REPAIR OF REAR INNER PANEL.		1,000.00	800.00
	TO APPLY ANTI RUST COAT AND AFFECTED AREAS.		120.00	30.00
	TO CHECK WIRING.		120.00	30.00
	WELDING AND CUTTING OF AFFECTED PANELS, INCLUDING CHASSIS ALIGNMENT. (NPA)	NOT NECESSARY	-	-
	SPRAY PAINTING FOR FRONT AND REAR PORTIONS AFFECTED PARTS.		1,200.00	600.00
	TO APPLY WATERPROOFING SEALER ON END PANELS.		120.00	30.00
	DIAGNOSE ECU SYSTEM AND RESET ERROR CODE.		120.00	30.00
	3D WHEEL ALIGNMENT.	NOT NECESSARY	180.00	-
			2,860.00	1,520.00

Report Ref No. CS/INC20011826/Evf3e2



Page No.:2 of 2

GRAND TOTAL	9,367.84	4,232.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		3,400.00

Report Ref No. CS/INC20011826/Evf3e2



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser