

31	ANTENNA		1	MKD47-67-6NXA		\$	111.10	
32	CLIP ,ANTENNA		1	MKD45-67-6NYA		\$	2.70	
33	CAMERA-BACK		1	MD24M-67-RC0		\$	793.80	
34	SILENCER		1	MPEG8-40-100A		\$	1,349.30	
35	HANGER, SILENCER		4	MBP47-40-061A		\$	140.00	
36	CONVERTER		1	MPEG8-20-55X		\$	1,278.70	
37	HANGER, COVERTER		1	MKL16-40-061		\$	28.40	
38	RUBBER, HANGER		2	MPE70-40-061		\$	57.00	
39	GASKET, EXHAUST		2	MP549-40-305		\$	30.80	
SUPPLEMENTARY ITEMS:								
1	GASKET LHS, TAILGATE	ADD	1	MDB3D-51-3J8	<i>NEW</i>	\$	41.30	\$ 41.30
2	GASKET RHS, TAILGATE	ADD	1	MDB3D-51-3H8	<i>NEW</i>	\$	41.30	\$ 41.30
TOTAL PARTS						\$	3,431.50	\$ 7,730.60
TOTAL PARTS COST						\$	3,431.50	\$ 7,730.60

Labour Description

1	MZ-BR-REAR04	TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND TAILGATE.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$	1,320.00	\$	2,640.00
2	MZ-SP-SREAR4	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND TAILGATE.	\$	1,575.00	\$	2,520.00
3	MZ-BR-SPOILER	TO REMOVE & REFIX SPOILER TAILGATE	\$	180.00	\$	180.00
4	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	\$	200.00	\$	560.00
5	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	\$	120.00	\$	120.00
6	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.	\$	330.00	\$	330.00
7	MZ-BR-EXASSY	TO REMOVE & INSTALL REAR EXHAUST ASSY.			\$	990.00
8	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	\$	180.00	\$	330.00
9	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	\$	180.00	\$	330.00
10	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.			\$	70.00
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$	120.00	\$	250.00
12	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$	120.00	\$	250.00