

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

MS FIRST CAPITAL INSURANCE LIMITED
 6 RAFFLES QUAY #21-00
 SINGAPORE 048580

Attention : Motor Claim Department
 Contact : 65073848 Fax No. : 65073849

Estimate : TP20/039

Date : 23/11/2020
 Vehicle Num. : SLN 9527Y
 Make/Model : MAZDA 6-2016
 Chassis/Eng# : JM6GL1071H0107340/PE20848533
 Accident Date : 30/10/2020
 Claim No. :
 Reference : LYB/SLN9527Y/MSFirst/tp/si
 Policy No. :

Not Attached
11 Amp &
Pushing After Paint
3 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

NETT ITEMS :				
1.	1	FRONT HEADLAMP/RH		1,950.00 ✓
2.	2	FRONT HEADLAMP BRACKET/RH	112.00	224.00 ✓
3.	1	FRONT BUMPER		895.90 ✓
4.	2	FRONT BUMPER RETAINER	112.00	224.00 ✓
5.	1	FRONT BUMPER SIDE MLDG	89.60	89.60 ✓
6.	1	FRONT BUMPER LOWER GRILLE/CENTRE		119.60 ✓
7.	1	FRONT BUMPER REINFORCEMENT		198.20 ✓
8.	1	FRONT GRILLE		566.50 ✓
9.	2	FRONT GRILLE CHROME LOWER		425.30 ✓
10.	8	FRONT GRILLE CLIPS	112.00	896.00 ✓
11.	1	FRONT GRILLE EMBLEM	3.00	3.00 ✓
12.	1	FRONT RADIATOR TOP PANEL		128.70 ✓
13.	1	FRONT WIPER TANK		319.60 ✓
14.	1	FRONT FOG LAMP COVER/RH		89.60 ✓
Nett Total S\$:				5,434.50
10.00% Discount S\$:				543.45
				4,891.05

SPECIAL NETT ITEMS :				
1.	2 /	FRONT BUMPER SENSOR	220.00	440.00 ✓
2.	4	FRONT RIVETS	5.00	20.00 ✓
3.	1 SET	FRONT NO PLATE (EMBOSS) + HOLDER		55.00 X
Special Nett Total S\$:				515.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONTINUE / ...

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

MS FIRST CAPITAL INSURANCE LIMITED
 6 RAFFLES QUAY #21-00
 SINGAPORE 048580

Attention : Motor Claim Department
 Contact : 65073848 Fax No. : 65073849

Estimate : TP20/039

Date : 23/11/2020
 Vehicle Num. : SLN 9527Y
 Make/Model : MAZDA 6-2016
 Chassis/Eng# : JM6GL1071H0107340/PE20848533
 Accident Date : 30/10/2020
 Claim No. :
 Reference : LYB/SLN9527Y/MSFirst/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		TO FOCUS HEADLAMP & CHECK HEADLAMP WIRING FUNCTION	55.00	201
		TO REPLACE FRT SENSOR & CHECK SENSOR WIRING	120.00	601
		TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS	120.00	X
		TO COMPUTERISE WHEEL ALIGNMENT	120.00	X
		TO REPAIR PANEL BEAT, RE-STRAIGHTEN ON FRT SUPPORT PANEL, LABOUR TO REPLACE ABOVE PARTS	700.00	3001
		TO PUTTY, PRIMER & SPRAY PAINT ON FRT BUMPER, FRT SENSOR FRT RADIATOR TOP PANEL, RIGHT FRT AFFECTED FENDER & FRT AFFECTED BONNET USING 2K PAINT	1,200.00	4001
		Labour Total S\$:	2,315.00	

E. & O.E.

Total S\$: 7,721.05

=====



for LIM YEW BOO SPRAY PAINT CO.