

AERO GARAGE PTE LTD

Blk 160, Sin Ming Drive, #08-07 Sin Ming AutoCity, Singapore 575722
Tel : 6266 9511 Fax : 6266 9512

Vehicle No : SCL9119J
Vehicle Model : Renault Fluence

Date : 02.11.2020

Estimate Repair Cost

No.	Qty	Parts List Items			
1	1	Rear door LH	1471.30	Ry \$	1,830.00 ✓
2	1	Rear door outer handle LH		Ry \$	240.00 ✓
3	1	Rear door lock LH	420	\$ Ry	580.00 ✓
4	2	Rear door hinges LH		\$ Ry	190.00 X
5	1	Rear door inner handle LH		\$ Ry	102.00 X
6	1	Rear door weatherstrip LH		\$ Ry	190.00 X
7	1	Rear door inner trim LH	865	myth Ry \$	1,430.00 ✓
8	1	Rear door regulator LH	680	Distm \$	880.00 ✓
9	1	Rear door windscreen moulding LH		\$ Ry	120.00 ✓
10	1	Rear door pillar LH		\$ Ry	170.00 ✓
11	1	Taillamp LH	Ry 552.00	cm \$	2,019.00 ✓
12	1	Rear fender LH	Ry 1750	Ry \$	2,880.00 ✓
13	1	Rear fender inner shield LH		\$ Ry	340.00 X
14	1	Rear fender inner trim LH		\$ Ry	970.00 X
Total				\$	11,941.00

Labour

1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$	2,000.00	800
2	To putty and respray painting on affected areas.	\$	1,200.00	500
3	To remove, replace rear door and fender fittings to facilitate repair.	\$	350.00	60
4	To remove, replace rear cushion and rear windscreen glass.	\$	300.00	200
5	To check wiring and lightings.	\$	80.00	20

Total Labour \$ 3,930.00

Total Parts and Labour \$ 15,871.00

Not Authorized
11/11/20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair After Paint
8 days