

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0826/2020/NS
DATE : 2-Nov-20
WIP : 56207

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR TAN JUN XIAN SHAWN
ADDRESS : BLK 620 BUKIT PANJANG RING ROAD
#15-822
SINGAPORE 670620
TELEPHONE : HP +65 97894220
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070149949
VEHICLE NO : SMV 8306 X
MODEL CODE : AUDI A3 SPORTSBACK 1.4 TFS
MODEL YEAR : 22/10/2020
ENGINE NO : CZE 866338
CHASSIS NO : WAUZZZ8V81A088972
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Oct-20
PLACE OF ACCIDENT : CAR PARK BUKIT BATOK EAST AVE 6

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 8306 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE ARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATUE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X X
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGAMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	500 ✓
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$ 2,000.00	1100 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,002.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 8306 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>torn</i>	\$	1,842.00	✓ 1473.60
2 FRONT BUMPER FIXING PARTS <i>Ne n</i>	\$	185.00	x
3 FRONT BUMPER GUIDE SECTION - LH <i>Day d</i>	\$	38.00	✓ 30.16
4 FRONT BUMPER GRILLE - CENTRE <i>Ne n</i>	\$	159.00	+
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>torn</i>	\$	293.00	✓ 234.40
6 FRONT BUMPER CLOSING ELEMENT - LH <i>Ne Ne n</i>	\$	293.00	? x
7 RADIATOR GRILLE <i>crushed</i>	\$	1,406.00	✓ 1124.80
8 RADIATOR GRILLE CLOSING ELEMENT <i>Ne Ne n</i>	\$	189.00	? x
9 AIRCON STICKER	NEC \$	8.00	✓ 5.68
10 CAUTION SIGN STICKER <i>3 new</i>	NEC \$	14.00	✓ 10.80
11 FRONT BUMPER AIR GUIDE GRILLE - LH <i>Ne n</i>	\$	186.00	+
12 FRONT REINFORCEMENT BEAM	\$	715.00	+
13 FRONT BUMPER FOAM FILLER PIECE <i>Ne n</i>	\$	187.00	+
14 FOAM FILLER PIECE COVER	\$	121.00	+
15 SIGNAL HORN - LH HIGH TONE <i>Ne n</i>	\$	197.00	+
16 FRONT FENDER - LH <i>Rep</i>	\$	841.00	+
17 FRONT FENDER ATTACHMENT PARTS	\$	71.00	+
18 FRONT FENDER BRACKET - LH	\$	47.00	+
19 FRONT FENDER BRACE	\$	95.00	+
20 FRONT FENDER CLOSING ELEMENT - LH	\$	61.00	+
SUB TOTAL SPARE PARTS	:	\$ 6,948.00	

PREMIUM AUTOMOBILES



5 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 8306 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 WHEEL HOUSING LINER - LH <i>to in</i>	\$	167.00	✓ 133.20
22 WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not Recs</i>		57.00	? X
23 LED HEADLIGHT - LH <i>Not Rec</i>	\$	5,455.00	? X
24 LIFT CYLINDER - LH <i>Not Rec</i>	\$	141.00	? X
25 LIFT CYLINDER HOSE <i>Not Rec</i>	\$	67.00	? X
26 WASH WATER RESERVOIR <i>green</i>	\$	202.00	+
27 WASH WATER RESERVOIR PUMP <i>green</i>	\$	151.00	+
28 RADIATOR AIR GUIDE - LH <i>Delivered</i>	\$	24.00	: 19.20 ✓
29 FRONT NO PLATE <i>Rec</i>	S/N \$	60.00	✓
30 SUNDRIES <i>Rec</i>	\$	200.00	? 30.16 ✓
TOTAL SPARE PARTS	:	\$ 13,472.00	
TOTAL LABOUR CHARGES	:	\$ 5,002.00	
GRAND TOTAL	:	\$ 18,474.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



5 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: Adrian L.

SURVEYED DATE

: 02/11/20

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

: Not Authorised, 03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT