

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jenny Lew

Date: 03 Nov 2020

Preliminary Advice

Vehicle No	: SMK763U	Accident Date	: 29/10/2020
Make	: VOLVO S60	Policy No.	: DMPCSNW00068042000
Assignment Date	: 02/11/2020	Excess	: S\$100.00
Date of Inspection	: 03/11/2020	Est. Duration of Repair	: 12
Inspection At	: Ding Auto Pte Ltd (HQ) Blk 10, #01-20, Sin Ming Industrial Estate Sector C Singapore 575645		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,866.67
Revised Amount	:S\$	18,250.67
Check Items (Estimated)	:S\$	3,840.00
Total	:S\$	22,090.67

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	30,500.00
COE / PARF Rebate	:S\$	25,052.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,448.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer proposed \$10,000.00 to repair the vehicle on lump sum basis.