













PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0451-19-TCA

14 October 2019

ACCIDENT VEHICLE SURVEY REPORT

Keok Su Seng
Blk 893A Woodlands Drive 50 #10-123
Singapore 730893

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SMD9330M	<i>Odometer:</i>	10569km
<i>Make & Model:</i>	Audi Q2	<i>Colour:</i>	Grey
<i>Chassis number:</i>	WAUZZZGA0JA084734	<i>Date of accident:</i>	04/02/2019
<i>Year of Regn.:</i>	12/09/2018	<i>Date inspected:</i>	18/02/2019
<i>Repairer at:</i>	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	26/02/2019

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.















