

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 28 Dec 2020

Preliminary Advice

Insured Vehicle No	: SLX9638H	Accident Date	: 30/10/2020
TP Vehicle No	: SLV6353J	Assignment Date	: 03/11/2020
Make	: HONDA CIVIC	Est. Duration of Repair	: 4
Date of Inspection	: 09/11/2020		
Inspection At	: Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,379.16
Revised Amount	:S\$	2,980.72
Check Items (Estimated)	:S\$	285.95
Total	:S\$	3,266.67

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP