

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368 Email: service@smemotor.com.sg

GST:201119451E RCB NO:201119451E

M/S : GREAT AMERICAN Insurance Company
3 Temasek Ave #16-01
CENTENNIAL TOWER
Singapore 039190

TEL: FAX:
ATTN: Motor Claim Department
Your Ref No : 20/GA/OD-416(10)
Claim Type : OD CLAIM
Accident Date : 29/10/2020

Claim No :
No : EST20111301
Date : 13/11/2020
Policy No : MOMVP000004073-00-000
Veh Reg No : SDZ8863P
Make / Model : LEXUS ES300
Chasis No : 0
Engine No:
Reg. No :

ESTIMATE FOR VEHICLE NO: SDZ8863P

Discription	Quantity	List Price	Amount
<u>Cost Price</u>			S\$ S\$
1 REAR RH WHEEL HUB	1 PC		\$395.00
			<u>\$395.00</u>
	Add 10%		<u>\$39.50</u>
			<u>\$434.50</u>

Parts 3862
+10% 4248.20
SN 175
LC 1385

5808.20
- 15%

4s 4950
=

Amount Before Excess	\$434.50
Less Excess	\$0.00
Amount Before GST	\$434.50
Add GST @7%	\$30.42
Total Amount Payable	<u>\$464.92</u>

For SME MOTOR PTE LTD

13/11/2020

AUTHORISED SIGNATURE

VEHICLE NO.: SDZ8863P
 MAKE: LEXUS
 MODEL: ES300
 YEAR OF MAKE: 2013
 CHASSIS NO.: JTHBW1GG002039044
 SUPPLIERS :

S/N	Parts Description	QTY	Amount
PARTS			
1	REAR RH SHOCK ABSORBER	1	\$290.00
2	REAR RH LOWER ARM	1	\$175.00
3	REAR RH TRAILING ARM	1	\$175.00
4	REAR RH KNUCKLE ARM	1	\$325.00
5	REAR RH KNUCKLE BEARING	1	\$400.00
6	REAR RH UPPER ARM	1	\$175.00
7	REAR RH SPORTS RIM	1	\$1,850.00
8	REAR RH FENDER INNER COWLING	1	\$120.00
9	INNER COWLING CLIP	10	\$25.00
10	REAR RH DOOR	1	\$750.00
11	REAR RH DOOR TOP STICKER (2PCS)	2	\$110.00
12	REAR RH DOOR 'HYBRID' EMBLEM	1	\$55.00
13	REAR RH DOOR INNER RUBBER	1	\$165.00
14	RH SIDE SKIRT	1	\$350.00
15	RH SIDE SKIRT CLIP	12	\$42.00
TOTAL PARTS			\$5,007.00
Rev RH wheel hub \$395. 10% Mark Up:			\$500.70
			\$5,507.70
S/N			
1	REAR RH TYRE	1 <i>175</i>	\$250.00
TOTAL S/N			\$250.00
LABOUR :			
1	WIRE CHECKING		\$30.00
2	REMOVE & REFIX REAR UNDERCARRIAGE		\$200.00
3	4 WHEEL ALIGNMENT		\$65.00
4	TRANSFER DOOR COMPONENTS FROM OLD TO NEW		\$120.00
5	WHEEL BALANCING		\$50.00
6	LABOUR CHARGE		\$650.00
7	SPRAY PAINTING		\$650.00
TOTAL LABOUR			\$1,765.00
			\$7,522.70
			\$526.59
			\$8,049.29

?
?
?
?
?
?
?
dd ✓
de ✓
ne ✓
bt ✓
ne ✓
ne ✓
de ✓
ne ✓
3467

ent ✓ 70%

✓
150? photo
✓
60
30.
600
600.

1385

Lik Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Taufik 97495749
 Not Authorise 6/4/20.
 Ex: hbq 6 days
 Lumpsum Resurvey after repair.
 TOTAL
 GST 7%
 taufik@lkhando.com.