



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Ref: CS/GAI20011975/T1cd3e2

Date: 16/03/2021

Code: GAI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SDZ 8863P
Policy No.	MOMVP000004073-00-000	Coverage (\$)	0.00
Claim No.	CLMOMVP000001105	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	03/11/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA LEXUS ES300H	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTHBW1GG002039044	Colour	GREY
Odometer	145203 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	MICHELIN	5 mm
L/H Front Tyre	215/55 R17	MICHELIN	5 mm
R/H Rear Tyre	215/55 R17	MICHELIN	5 mm
L/H Rear Tyre	215/55 R17	MICHELIN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION AND UNDERCARRIAGE.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/10/2020	Inspection Date	06/11/2020
Survey held at	1 WALLICH STREET#35-01 GUOCO TOWER		
Repairer	SME MOTOR PTE LTD		

5a. Remarks

A)THE MARKET VALUE IS S\$70,000.00(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**