

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ **After-Paint:** _____
 Contacts : _____

Vehicle Nos : **SMQ 8773 G**
 Made : Honda
 Model : Vezel
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front bumper	1	\$ 1,050.00	\$ 1,050.00 817.90
2	Front bumper lower	1	\$ 485.60	\$ 485.60 458.30
3	Front bumper side retainer	2	\$ 65.00 72.00	\$ 144.00 130.00
4	Front bumper reinforcement	1	\$ 486.00	\$ 486.00 321.70
5	Front bumper fog lamp	2	\$ 456.70 445.00	\$ 913.40 890.00
6	Front bumper fog lamp garnish	2	\$ 126.20 105.00	\$ 252.40 210.00
7	Front bumper grille	1	\$ 582.30	\$ 582.30 440.50
8	Front bumper grille logo	1	\$ 89.00	\$ 89.00 38.80
9	Front bumper grille base	1	\$ 413.60	\$ 413.60
10	Front bumper grille outer chrome garnish	1	\$ 368.00	\$ 368.00 ✓ 368.00
11	Front bumper lower grille	1	\$ 198.60	\$ 198.60 123.70
12	Front bumper grille top bracket side	2	\$ 87.30 45.80	\$ 174.60 91.60
13	Front bumper grille top bracket centre	1	\$ 198.00	\$ 198.00 38.70
14	Front bumper tow cap	1	\$ 83.20	\$ 83.20 46.80
15	Front license plate	1	\$ 98.00	\$ 98.00 50.00
16	Headlamp assy	2	\$ 2,145.90	\$ 4,291.80 3,847.00
17	Headlamp bracket	2	\$ 76.00 35.00	\$ 152.00 70.00
18	Bonnet	1	\$ 1,034.70	\$ 1,034.70 ✓ 1,034.70
19	Bonnet lock assy	1	\$ 234.60	\$ 234.60 109.50
20	Bonnet insulator	1	\$ 396.40	\$ 396.40 211.30
21	Bonnet hinge	2	\$ 89.00	\$ 178.00 ✓ 178.00
22	Bonnet rubber (short)	2	\$ 91.00 37.50	\$ 182.00 75.00
23	Bonnet rubber (long)	1	\$ 135.00	\$ 135.00 ✓ 135.00
24	Front support panel	1	\$ 898.00	\$ 898.00 576.20
25	Front support panel top garnish	1	\$ 185.00	\$ 185.00 ✓ 185.00
26	Front support panel side garnish	2	\$ 84.60	\$ 169.20
27	Front fender LH	1	\$ 756.00	\$ 1,512.00
28	Front fender inner cowling	2	\$ 134.20	\$ 268.40 130.00
29	Front fender arch garnish	2	\$ 128.90	\$ 257.80 ✓ 257.80
30	Front door	1	\$ 1,280.00	\$ 2,560.00
31	Front door black tape	2	\$ 68.00	\$ 136.00
32	Front wiper washer tank	1	\$ 265.80	\$ 265.80 ✓ 265.80
33	Front wiper washer tank motor	1	\$ 150.00	\$ 150.00
34	Front wiper garnish	1	\$ 425.60	\$ 425.60
35	Radiator	1	\$ 987.90	\$ 987.90 ✓ 987.90
36	Radiator fan motor	2	\$ 538.00	\$ 1,076.00
37	Radiator fan cowling	2	\$ 215.60 175.00	\$ 431.20 350.00
38	Radiator fan blade	2	\$ 116.00	\$ 232.00

12/2019

BR ✓
 BR ✓
 NEC ✓
 BR ✓
 BR ✓
 Cut ✓
 BR ✓
 NEC ✓
 BR NISX
 BR ✓
 DD ✓
 BT ✓
 BR ✓
 BT ✓
 } NEC
 DD ✓
 BR ✓
 NDX
 DD ✓
 TN ✓
 BR ✓
 DD RX
 NNX
 BR ✓
 NDX
 NDX
 BT ✓
 NDX
 BR ✓
 NDX

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ **After-Paint:** _____
 Contacts : _____

Vehicle Nos : SMQ 8773 G
 Made : Honda
 Model : Vezel
 Chassis No : _____

Supplementary Report

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Headlamp outer chrome garnish	2	\$ 110.00	\$ 220.00 ✓220.00
2	Intake manifold	1	\$ 880.00	\$ 880.00 ✓880.00
Parts Sub Total :				\$ 1,100.00 1,100.00
20% Discount				\$ 220.00
PARTS TOTAL :				\$ 880.00 880.00

MISV
CUT ✓

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Intake manifold gasket	1	\$ 60.00	\$ 60.00
SPECIAL NETT TOTAL :				\$ 60.00 60.00

NECV ✓

Nos.	LABOUR	S\$
1	R&R intake manifold	\$ 80.00 150.00 ✓
LABOUR TOTAL :		\$ 80.00 150.00

Resurvey 5/11/2020
 1430 hrs
 Telem Lin

PARTS TOTAL : \$ 880.00
 SPECIAL NETT TOTAL : \$ 60.00
 LABOUR TOTAL : \$ ~~80.00~~ -150.00
GRAND TOTAL : \$ ~~1020.00~~ 1,090.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

39	Radiator top hose	1	\$	148.60	\$	148.60	} NDX
40	Radiator lower hose	1	\$	159.30	\$	159.30	
41	Fan belt	1	\$	194.50	\$	194.50	} NDX
42	Aircon compressor	1	\$	853.20	\$	853.20	} NDX
43	Aircon compressor belt	1	\$	354.00	\$	354.00	} NDX
44	Aircon condenser	1	\$	985.00	\$	985.00 788.00	} BR ✓
45	Aircon suction hose	1	\$	398.00	\$	398.00 198.00	} BT ✓
46	Aircon discharge hose	1	\$	352.00	\$	352.00 275.00	
47	Air duct	1	\$	86.90	\$	86.90	} NDX
48	Air cleaner box	1	\$	482.10	\$	482.10	} BT ✓
49	Front chassis member	1	\$	1,985.60	\$	1,985.60 1510.00	
50	Alternator assy	1	\$	985.20	\$	985.20	} NDX
51	Starter motor assy	1	\$	954.60	\$	954.60	
Parts Sub Total :					\$	29,635.10	
20% Discount					\$	5,927.02	
PARTS TOTAL :					\$	23,708.08	

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$			
1	Sundries	1	\$	80.00	\$ 80.00	} NDX	
2	Front bumper clips	1	\$	50.00	\$ 30.00 50.00		
3	Front bumper lower clips	1	\$	50.00	\$ 30.00 50.00	} NEC ✓	
4	Front bumper fog lamp garnish clips	2	\$	50.00	\$ 30.00 100.00		
5	Front bumper grille clips	1	\$	50.00	\$ 20.00 50.00	} NEC ✓	
6	Front bumper lower grille clips	1	\$	50.00	\$ 30.00 50.00		
7	Bonnet sealant	1	\$	100.00	\$ 40.00 100.00	} NEC ✓	
8	Bonnet insulator clips	1	\$	50.00	\$ 30.00 50.00		
9	Bonnet rubber clips	3	\$	50.00	\$ 60.00 150.00	} NEC ✓	
10	Bonnet air duct	1	\$	250.00	\$ 250.00	} NDX	
11	Front support panel sealant	1	\$	100.00	\$ 100.00	} NDX	
12	Front support panel top garnish clips	1	\$	50.00	\$ 30.00 50.00	} NEC ✓	
13	Front support panel side garnish clips	2	\$	50.00	\$ 40.00 100.00	} NEC ✓	
14	Front fender sealant	LH 1	\$	100.00	\$ 60.00 200.00		
15	Front fender inner cowling clips	2	\$	50.00	\$ 60.00 100.00	} NEC ✓	
16	Front fender arch garnish clips	2	\$	50.00	\$ 60.00 100.00	} NEC ✓	
17	Front door sealant	2	\$	100.00	\$ 200.00	} NDX	
18	Front wiper garnish clips	1	\$	50.00	\$ 30.00 50.00	} NEC ✓	
19	Horn	1	\$	80.00	\$ 80.00	} NDX	
20	Radiator coolant	1	\$	80.00	\$ 40.00 80.00	} NEC ✓	
21	Aircon fluid	1	\$	80.00	\$ 40.00 80.00	} NEC ✓	
22	Brake fluid	1	\$	80.00	\$ 80.00	} NDX	
23	Number plate with casing	1	\$	80.00	\$ 50.00 80.00	} BR ✓	
SPECIAL NETT TOTAL :					\$	2,230.00	

740.00

Nos.	LABOUR	S\$	
1	R&R bonnet component	\$ 60.00	150.00
2	R&R wiper garnish	\$ 50.00	150.00
3	R&R ABS pump	\$	250.00
4	Check wiring	\$ 40.00	100.00
5	R&R radiator	\$ 70.00	150.00
6	R&R condenser	\$ 70.00	150.00
7	R&R aircon compressor	\$	150.00
8	R&R alternator assy	\$ 50.00	150.00
9	R&R starter motor assy	\$	150.00
10	Diagnostic and reset fault code	\$ 120.00	300.00
11	Upholstery	\$	300.00
12	Mount work bench	\$	300.00
13	Chasis alignment	\$ 200.00	300.00
14	Panel beating	\$ 1600.00	2,000.00
15	Rust proofing	\$ 80.00	200.00
16	Spray painting	\$ 1400.00	2,000.00
LABOUR TOTAL :		\$ 3820.00	6,800.00

/
 /
 NNX
 /
 /
 NNX
 /
 NNX
 /
 /
 /
 /

Survey Resurvey
 4/11/2020 5/11/2020
 1530 hrs 1420 hrs
 Team M Team M

PARTS TOTAL : \$ 23,708.08
 SPECIAL NETT TOTAL : \$ 2,230.00
 LABOUR TOTAL : \$ 6,800.00
GRAND TOTAL : \$ 32,738.08

Repair days 12
 Part by Part Repair

PARTS 13,568.80
 S/N 740.00
 LABOUR 3,820.00

 18,128.80
 @ 20% 3,625.76

 14,503.04

4s 14,500/2

LKK Auto Consultants hence notify
the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

 Acknowledged by Repairer
 Signature:
 Date:

Team M
 10/11/2020