

Bifrost Auto Pte Ltd

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: 65 64524457 / Fax: +65 64524584

CO. Reg. No.: 201929175W

Model : **Toyota Hiace Commuter 2.8GL AT**Registration No : **PC 7838 Z**Chassis No: **GDH2232001106**Year of Manufacturing: **2018**

S/No	Qty	Items	Unit Price	Amount
1	1	Front Bumper / <i>at</i>		\$ 671.50 - 589.6
2	2	Front Bumper Retainer X		\$ 1212.80 -
3	2	Front Bumper Bracket X <i>NN</i>		\$ - -
4	2	Front Bumper Towing Cover X <i>NN</i>		\$ 26.90 -
5	1	Front Bumper Grille Assy / <i>at</i>		\$ 386.40 - 208.9
6	1	Front Reinforcement X <i>NN</i>		\$ 480.20 -
7	1	Headlight (RH) / <i>BR</i>		\$ 2679.20 - 1914.2
8	1	Headlight (LH) X <i>NN</i>		\$ 2679.20 -
9	1	Front Support Panel <i>repair x</i>		\$ 409.30 -
10	1	Radiator X		\$ 2980.30 -
11	1	Condenser X <i>NN</i>		\$ 1821.50 -
				\$ - 2712.7
				-25% \$ - 2034.52
Total for spare parts				\$ -

Special Nett

1	1	Front Bumper Clip set / <i>at</i>	\$ 50.00	\$ 50.00 30
2	1	Front Lower Bumper <i>repair x</i>	\$ 1,250.00	\$ 1,250.00
Total for SP				\$ 1,300.00
Sub-Total for Parts :				\$ 1,300.00

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.	\$	900.00 300
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	1,200.00 400
3		To check wiring system to facilitate repair and refit the same	\$	60.00 30
4		Apply rust proofing on the adjacent panels	\$	80.00 X
5		To supply under coating / putty on parts replaced	\$	50.00 X
6		To perform water seepage test after repair	\$	80.00 X
7		To conduct headlight focus	\$	80.00 X
8		Remove and replace air-con condenser, pipes and radiator, vacuum air-con system	\$	150.00 X
TOTAL AMOUNT :				\$ 2,600.00
OVERALL COST :				\$ 3,900.00

3 Days .

Comp Sm Repair

After repair photos.

Gmo Arif.

11/11/2020.

2794.52

-20%: 2200

LJK Auto Consultants hence notify
the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: