



KGC WORKSHOP PTE LTD

Since 1967

Sincere • Secure • Satisfaction

Co.Reg.No.: 201719986M

GST.Reg.No.: 201719986M

AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way,

#09-16 AIG Building,

Singapore 079120.

Ref No : TP 201104

Date : 14/12/2020

No Of Page : 1/1

Registration No : SLQ 4348P

Model : Hyundai Tucson

Job No : 201104

Accident Date : 01/11/2020

REPAIR BILL OF SLQ 4348P

Cost Of Repair	\$	2,134.00
ADD 7% GST	\$	149.38
TOTAL REPAIR COSTS	\$	2,283.38

Dollars : Two Thousand Two Hundred Eighty-Three And Cents Thirty-Eight Only.

 **KGC WORKSHOP**
Sincere • Secure • Satisfaction
14 Ang Mo Kio St.63, Block B (S) 569116
Tel: 6453 6279 / 6456 5410
Email: contact@kgeworkshop.com.sg

(Signature / Company Stamp)

KGC Workshop Pte Ltd

14 Ang Mo Kio St 63, Block B (569116)

Office : 6453 6279 Fax : 6456 5410