



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Date: 10th November 2020

Our Ref: CS1/TP20012022/Kvf3s2

M/s Trans-Cab Auto Services Pte Ltd

No.2 Ang Mo Kio Street 63
Singapore 569111

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SHD 388R
ACCIDENT DATE: 01/02/2014**

We thank you for your instruction on 04/11/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHD 388R from M/s Trans-Cab Auto Services Pte Ltd.
- b) Singapore Accident Statement of Vehicle SHD 388R.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -
Registration Number : SHD 388R
Make & Model : Mercedes-Benz E220 CDI (A)
Chassis Number : WDB2110082B179564
2. We recommend that the repairs of the entire damage require about 14 (Fourteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.