





PRE-REPAIR INSPECTION REPORT				
MS FIRST CAPITAL INSURANCE LTD		Ref: CS3/FCI20012030/Evd3e2		
36 ROBINSON ROAD		Date: 10-11-2020		
#16-01 CITY HOUSESINGAPORE 068877				
		Code: FCI2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHB 6649J	Veh. Inspected	FBL 5529Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D20004472MFSH	Excess (\$)	0.00	
Assign From	SANGHILAN VIC	Assign Date	04/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA NC750X	c.c	745	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RC901001181	Colour	RED	
Odometer	201104 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70 ZR17	MICHELIN	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60 ZR17	MICHELIN	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.			
5. General Information				
Accident Date	02/11/2020	Inspect Date / Time	04/11/2020 (01:07 PM)	
Survey held at	149 SHUN LI INDUSTRIAL PARK			
Repairer	GARAGE 13 PTE LTD			
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$10,000.00			

Report Ref No. CS3/FCI20012030/Evd3e2

Inspected By



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.