OMFORTDELGRO PTE LTD

VEHICLE NO

SHD4059P

MAKE

04/11/20

DDEL	IONIQ G3	CHIANG/		Amount
Qty	Parts Description/ Labour	Туре	Unit Price	\$459.40
	IREAR RUMPER V R		\$55.80	\$111.60
	1 REAR BUMPER BRACKET LH/RH X AIAI	, Z	\$33.80	\$294.80
	1 REAR REINFORCEMENT X AM	2.7	\$2.20	\$22.00
	ADEAR RUMPER CUPS X M		\$2.20	\$451.25
	1 REAR BUMPER CENTRE MOULDING / (4)	*		\$201.00
	1 FOG LAMP 1 X AIM	¥		\$1,540.05
	*			\$308.01
	20.00		361	\$1,232.04
	DISCOUNTED TOTA	4		9
			a a	\$135.7
	1 REVERSE SENSOR X MM			\$50.0
	JOURADER MAT X AVV	- "		\$50.0
	REAR NUMBERPLATE W/HOLDER		50	\$235.7
		R I	*	
	Labour Charge			\$640.0
	Panel Beating			\$300.0
	Spray Painting Charge	2 2 2	550	1 火 \$60.0
	Remove/refix reverse sensor		871	\$50.
	chack lighting			\$1,050.
	TOTAL LABO	UK		ω
			1 = 961	\$2,517
	ESTIMATE TO	TAU	- LE - L	
		1 200	44 S A	
		s v * ,		
				is avantum will

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Ster (LKK) WI A

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4/11/20,4.90/ 2 dys P/P MM