

TO :

FAX NO:

ESTIMATE REPORT

1ST Quotation

04/11/2020 18:41

JOB-NO: 50112926

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
 ADDRESS: 383 SIN MING DRIVE
 SINGAPORE 575717 0

CONTACT: 65533880
 64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHA9593X

TRANS: AUTO

CHASSIS: KMHLB41UMHU098316

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDGU706875

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHT AND PANEL BEAT ACCIDENT AREA	1.00	800.00	0.00	800.00		Y	600
2 RUST PROOFING	1.00	80.00	0.00	80.00		Y	40
3 SUNDRIES	1.00	50.00	0.00	50.00		Y	20
4 R&R RADIATOR & CONDENSER & TURBO INTERCOOLER	1.00	180.00	0.00	180.00		Y	100
5 VACUUM & TOP UP AIR COND GAS R-134A	1.00	150.00	0.00	150.00		Y	80
6 ADJUST HEADLAMP AIM	1.00	80.00	0.00	80.00		Y	Xnn
7 CHECK WIRING & LIGHTING SYSTEM	1.00	120.00	0.00	120.00		Y	30
8 RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00		Y	200
9 RESPRAY FRONT FENDER LH	1.00	250.00	0.00	250.00		Y	200
10 RESPRAY FRONT DOOR LH	1.00	250.00	0.00	250.00		Y	200
TOTAL:		2,210.00	0.00	2,210.00			

MATERIALS

1 FRONT BUMPER <i>scu</i>	1.00	599.68	119.94	479.74	L	Y	
2 FRONT BUMPER RETAINER LH <i>Xscr</i>	1.00	48.32	9.66	38.66	L	Y	
3 HEADLAMP LH <i>scu</i>	1.00	1,808.10	361.62	1,446.48	L	Y	
4 FRONT FENDER LH <i>bu</i>	1.00	656.50	131.30	525.20	L	Y	3474.12
5 FRONT FENDER INNER SHIELD LH <i>Xscr</i>	1.00	185.12	37.02	148.10	L	Y	
6 FRONT FENDER INNER BRACKET LH <i>Xscr</i>	1.00	45.12	9.02	36.10	L	Y	
7 FRONT WHEEL CAP LH <i>scu</i>	1.00	265.50	53.10	212.40	L	Y	
8 FRONT SUPPORT PANEL <i>cm</i>	1.00	962.87	192.57	770.30	L	Y	
9 FRONT BUMPER CLIP SET <i>scu</i>	1.00	50.00	0.00	50.00	S	Y	30
10 FRONT FENDER INNER SHIELD CLIP SET LH <i>Xm</i>	1.00	35.00	0.00	35.00	S	Y	
11 FRONT DOOR STICKER-COMFORT DELGRO LH <i>scu</i>	1.00	150.00	0.00	150.00	S	Y	100
12 RADIATOR COOLANT <i>gscu</i>	1.00	60.00	0.00	60.00	S	Y	170
TOTAL:		4,866.21	914.23	3,951.98			

TOTAL PARTS & LABOUR : 7,076.21 914.23 6,161.98

EXCESS/LOADING:\$ 0.00

No. Of Day:

*5 days*RE-SURVEY: BEFORE AFTER PAINTINGPART-BY-PART OR LUMP SUM:\$DATE OF SURVEY: *05 / 11 / 2020 @ 1550*

AIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

SURVEYED BY: Rahul

CONTACT NO: 90010068

FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: