

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd  
20 McCallum Street  
#09-01 Tokio Marine Centre  
Singapore 069046

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jeffrey Tay

Date: 20 Nov 2020

## **Preliminary Advice**

Insured Vehicle No	: SMK1991X	Accident Date	: 03/11/2020
TP Vehicle No	: SHA9593X	Assignment Date	: 04/11/2020
Make	: HYUNDAI I40	Est. Duration of Repair	: 5
Date of Inspection	: 05/11/2020		
Inspection At	: Ding Auto Pte Ltd (corporation Road) (HQ) 31 Corporation Road Singapore 649825		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,161.98
Revised Amount	:S\$	5,074.12
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,074.12
Lump Sum Repair	:S\$	4,050.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : TP : WP