

Jaslin Kok (LKK Auto)

From: Jaslin Kok (LKK Auto)
Sent: Friday, 13 November 2020 12:23 PM
To: Mekavathanan Sarangapani
Cc: Admin A; Hsiao Tong (LKKAuto); sherini@iii.com.sg; KKLau
Subject: RE: Incoming Claim Alerts - SBS6536H (TP) //LKK Ref: CC4/III20012081/Eps3
Attachments: TP VIDEO.MP4

Dear Mr Meka,

Enclosed a copy of the third party video for your easy reference. Kindly assist to upload TP video in merimen.

We have uploaded the estimate repair cost in Merimen as well.

Aside from that, please let us have your approval in liability.

Thank you.

Best Regards,

Jaslin Kok | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841 2157 | email: JaslinKok@lkkauto.com | fax: 6741 4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Thursday, 5 November 2020 1:28 PM
To: Mekavathanan Sarangapani <mekavathanan@iii.com.sg>
Cc: Sherini Pillai <sherini@iii.com.sg>; KKLau <kklau@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Re: Incoming Claim Alerts - SBS6536H (TP) //LKK Ref: CC4/III20012081/ps3

Hi Mr Meka,

We will request video footage from third party and update accordingly.

We are currently pending for survey and will upload the estimate repair cost in Merimen once it is ready. Thanks.

***Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.**

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742 3197 | email: chewht@lkkauto.com | fax: 6741 4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mekavathanan Sarangapani <mekavathanan@iii.com.sg>
Sent: Wednesday, 4 November 2020 6:29 PM
To: Sherini Pillai <sherini@iii.com.sg>; KKLau <kklau@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: FW: Incoming Claim Alerts - SBS6536H (TP)

Dear LKK team

Able to obtain the CCTV footage from TP Bus please . have you adjusted costs of repairs etc yet ?

Meka

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:			
Main Claimant:	GO AHEAD SINGAPORE PTE LTD		
Vehicle Reg. No.:	SBS6536H	Date of Loss:	30/10/2020 14:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SH6592B	Policy No. (Claimant):	
Repairer:	LexBuild International Pte Ltd (HQ) PROFILE 11 Tuas Bay Close, #04-02 West Star, 636996 Tuas - Tel: 6456 3533		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ACCUSER4] ... [Final Rpt due 13/11/2020]		

A; Insurance Particulars

Related Accident Reports					
<ul style="list-style-type: none"> SH6592B ... MCD620095682 submitted on 31/10/2020 08:42 to India International Insurance Pte Ltd ... [This is your Own Insurer Report] <ul style="list-style-type: none"> TP reported: SBS6536H. SBS6536H ... MGAL20096299 submitted on 03/11/2020 15:42 to MS First Capital Insurance Ltd ... [This TP report has been purchased] ... [CURRENTLY VIEWING] <ul style="list-style-type: none"> TP reported: SH6592B. 	<p>Accident Report Basic Information</p> <table border="1"> <thead> <tr> <th>File Ref No</th> <th>MGAL20096299</th> <th>Entry Date/Time</th> <th>02/11/2020 14:52</th> </tr> </thead> </table>	File Ref No	MGAL20096299	Entry Date/Time	02/11/2020 14:52
File Ref No	MGAL20096299	Entry Date/Time	02/11/2020 14:52		

B : Taxi's version :

Describe Circumstances of the Accident.

On the 30/10/2020 @ about 15:30hrs, I was driving out towards Haugang 91 21 direction with No passenger on board my taxi.

As I was driving, suddenly a Go-Ahead of SBS6536H grazed onto my taxi right front portion.


No injury at the point of accident.

C: Taxi's sketch plan

A = SH 6592B

HOUGANG ST 21

B = SBS 6536H
GO AHEAD



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Statement as per attached.

D: Scene of accident photos :





SCENE





		Licence & Expiry Date	
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TANG WAI YEE PHILIP	ID No.	S1799272D
Related Vehicle	SH6592B (Car)	Contact No.	96668936
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the above mentioned date, time and location, I was driving my vehicle (SBS6536H) along Hougang St 21. My vehicle came to a complete stop as the traffic light was red. I have checked my blindspot on the left and I saw, a blue taxi (SH6592D) stationed near my rear side of my vehicle. When the light turn green, I started my vehicle and the taxi did not give way thus collided on my vehicle. Collision on my rear left side of my vehicle with his right front of his vehicle.

My vehicle sustained scratch and dents marks along the left rear and centre and one tyre on the rear left had punctured marks. Myself and all 13 passengers did not sustain any injuries. My in-car camera footage is working and I have images of the incident.

The taxi sustained a few damages to the front right part of his vehicle. The taxi sustained scratches, fairing peeled off and broken headlight. The driver did not sustain any injuries.

Accident Photo



From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Wednesday, 4 November 2020 6:00 pm
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Incoming Claim Alerts - SBS6536H (TP)

This mail is associated with :
***SBS6536H**
[SH6592B]
TP
GO AHEAD SINGAPORE PTE LTD
Oct 30 2020 2:00PM

LexBuild International Pte Ltd

Dear Sir / Madam

There is an incoming claim with the following details:

Vehicle No: SBS6536H
Claim Type: TP
Date of Loss: 30/10/2020
Insured Name:
Workshop Name: LexBuild International Pte Ltd (HQ)

To view this record, please logon to www.merimen.com.sg

Merimen Online
sg-support@merimen.com

Please do not reply to this email as it is auto-generated

This is an auto-generated email. Do not reply to this email.

Sent by : Merimen Administrator (MERIMEN TECHNOLOGIES (SINGAPORE) PTE. LTD.)

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.