

9<sup>th</sup> November 2020

India International Insurance  
64 Cecil St,  
Singapore 049711

Attn: Claims Department

**Estimated Cost of Repair job for SBS6536H (Accident on 30/10/2020, HOUGANG ST 21 63221 - KOVAN HUB involving SBS6536H & SH6592B)**

We are pleased to submit herein, our quotation for your consideration.

		Qty.	Unit Price	Total Price	
1	Supply skilled labour to replace - LHS 2 <sup>nd</sup> bodypanel - Door Number 4 rubber (C type) - Exit Door frame assembly	2.5 day 2	\$880.00 500	\$2,200.00	1000
2	Supply skilled labour & Sika265 / Primer / activator to replace exit door number 3 & door number 4	2 day	\$880.00	\$1,760.00	X
3	Supply skilled painter & paint material to putty grinding & spraypaint - LHS 2 <sup>nd</sup> bodypanel (2pc) - LHS rear wheelarc panel (1pc) - LHS rear lower skirting (1pc)	3 portion (2 day)	\$800.00 Labour - 2050	\$3,200.00	1000
4	Supply electrician to replace 2 marker lamp	1 day	<del>\$200.00</del>	\$200.00	50
5	LHS 2 <sup>nd</sup> bodypanel	1 pc	\$4,725.27	\$4,725.27	✓
6	Door Number 4 rubber (C type)	1 pc	\$793.78	\$793.78	✓
7	Exit Door frame assembly (moulding)	1 pc	\$3,216.54	\$3,216.54	✓
8	Door glass number 3	1 pc	\$2,290.53	\$2,290.53	X
9	Door glass number 4	1 pc	\$2,290.53	\$2,290.53	X
10	Marker lamp	2 pcs	\$145.20	\$290.40	✓
11	SG <3 bus sticker	1 pc	\$50.00	\$50.00	30
12	Go-Ahead Singapore Sticker	1 pc	\$50.00	\$50.00	30
				<b>Total</b>	<b>\$ 21,067.05</b>
				<b>GST</b>	<b>\$ 1,474.69</b>
				<b>Grand Total</b>	<b>\$ 22,541.74</b>

**LexBuild International Pte. Ltd.**

11 Tuas Bay Close, #04-01/02 West Star,  
Singapore 636996

Tel: (65) 6456 3533, Fax: (65) 6456 3353

Website: www.LexBuild.com, Email: operations@LexBuild.com



杨通国际

LexBuild™

**Terms and Conditions:**

Payment Terms : 30 days upon invoice  
Quotation Validity : 30 days  
Lead-Time : 9 working days  
Price quoted subject to 7% GST

Yours faithfully

*Tien Yong Shun*

Tien Yong Shun  
HP: 9029 6574

Steve (LKK)

ML PL  
9/11/29

4 dys  
P/P

Ry Bel spy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


**LexBuild International Pte. Ltd.**

11 Tuas Bay Close, #04-01/02 West Star,  
Singapore 636996

Tel: (65) 6456 3533, Fax: (65) 6456 3353

Website: [www.LexBuild.com](http://www.LexBuild.com), Email: [operations@LexBuild.com](mailto:operations@LexBuild.com)

biSAFE  
STAR



ROC / CR / GST Reg No: 200004370R