

HWA SENG SPRAY PAINTING PTE LTD

160 Sin Ming Drive

#05-11 Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO : 202017045G)

TEL : 64533100

FAX : 62669932

Date of Accident : 01/11/2020

Your Insured
Vehicle NO: XE 5139R

Not Authorised

L1 Rep @
Respray After Paint

3 days

ESTIMATE REPAIR COSTS TO ISUZU NPR REG. NO. : YP 4243 J

S\$

1pc O/S Wing Mirror
 1pc O/S Wing Mirror Bracket
 1pc O/S Signal Lamp
 1pc O/S Corner Panel
 1pc O/S Headlamp
 1pc Front Panel
 1pc Emblem 'ISUZU'
 1pc Sticker 'Reward.NP'
 1pc Front Grille
 1pc Front Bumper
 1pc Front Bumper Reinforcement

mi 75.00 ✓
 mi 265.00 ✓
 cm 225.00 ✓
 cm 245.00 ✓
 my cm 350.00 ✓
 R 695.00 X
 R 89.00 ✓
 R 58.00 ✓
 my cm 435.00 ✓
 R 585.00 X
 R 365.00 X

3387.00

Less : 15%

508.05

2878.95

LABOUR & MISC CHARGES

Panel Knocking
 Spray Painting
 Wire Checking
 Labour to Remove & Install Front Windscreen
 Sealant & Clip
 Inner Seal
 Vacuum & Top Up Gas
 Labour to Remove Dashboard & Air Con to Facilitate Repair

700.00 400
 600.00 320
 60.00 20
 R 180.00 X
 R 100.00 X
 R 100.00 X
 R 120.00 X
 R 350.00 X

TOTAL

5088.95

HWA SENG SPRAY PAINTING PTE LTD
