

Date of Accident: 01/11/2020

Your Insured
Vehicle NO: XE 5139R

HWA SENG SPRAY PAINTING PTE LTD
160 Sin Ming Drive
#05-11 Sin Ming Autocity
SINGAPORE 575722
(COMPANY REGISTRATION NO : 202017045G)
TEL : 64533100
FAX : 62669932

ESTIMATE REPAIR COSTS TO ISUZU NPR REG. NO. : YP 4243 J

S\$

1pc	O/S Wing Mirror	75.00
1pc	O/S Wing Mirror Bracket	265.00
1pc	O/S Signal Lamp	225.00
1pc	O/S Corner Panel	245.00
1pc	O/S Headlamp	350.00
1pc	Front Panel	695.00
1pc	Emblem 'ISUZU'	89.00
1pc	Sticker 'Reward.NP'	58.00
1pc	Front Grille	435.00
1pc	Front Bumper	585.00
1pc	Front Bumper Reinforcement	365.00

3387.00

Less : 15%

508.05

2878.95

LABOUR & MISC CHARGES

Panel Knocking	700.00
Spray Painting	600.00
Wire Checking	60.00
Labour to Remove & Install Front Windscreen	180.00
Sealant & Clip	100.00
Inner Seal	100.00
Vacuum & Top Up Gas	120.00
Labour to Remove Dashboard & Air Con to Facilitate Repair	350.00

TOTAL

5088.95

HWA SENG SPRAY PAINTING PTE LTD

