



Pte Ltd

TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

REPAIR PERFORMANCE INVOICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice"
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

FIRST CAPITAL

Steve (LKK)
W/L AL
5/11/10, 12.00pm
5 dyi
LIS, M AL

Vehicle number GBJ5464K
Make / Model TOYOTA DYNA
Chassis number JTFAT35Y40K213234
Accident date 31/10/20
Reference 2011-07

Acknowledged by Repairer

Signature:

Date:

Qty Particulars

PARTS REPLACEMENT - LIST ITEMS

1	TAILGATE X R	1910.80
1	TAILGATE LOWER SIDE BRACKET LH X	304.70
1	TAILGATE LOWER SIDE BRACKET RH X	304.70
2	TAILGATE STOPPER X	55.00
4	TAILGATE LOWER HINGE X	105.00
1	TAILLAMP PANEL LH X / BT	242.65
1	TAILLAMP PANEL RH X / BT	242.65
1	TAILLAMP LH / OR	253.00
1	TAILLAMP RH / OR	253.00
1	REAR TAILGET LOWER MEMBER /	485.90
1	REAR NUMBER PLATE BRACKET / BT	196.90
2	REAR NUMBER PLATE LAMP X / CUT	97.00
1	SPARE TYRE CARRIER / BT	443.00
1	REAR EXHAUST / BT	977.50
2	EXHAUST MOUNTING / TN	42.40
1	REAR EMBLEM TOYOTA / NEC	120.00
1	REAR EMBLEM DYNA / NEC	55.00

6089.20

Less 25 % 1522.30

Subtotal 4566.90

Balance C/F

PARTS REPLACEMENT - SPECIAL NETT ITEMS

1 SET	REVERSE SENSOR / A Shark d	400.00
1	70KM/H / NK	70.00
1	13 PAX / NK	60.00
1	REAR NUMBER PLATE / BT	80.00
1	STEP BRACKET / BT	350.00
1	TAILGATE ALUMINIUM BOARD X	1200.00

Subtotal 2160.00

Balance C/F 6726.90

LABOUR AND MISCELLANEOUS CHARGES

Balance B/F

6726.90

1	CHECK REAR WIRING AND LIGHTING SYSTEM	60.00	30
2	REMOVE AND RENEW REAR EXHAUST	120.00	80
3	REMOVE AND REFIT REAR REVERSE SENSOR	200.00	30
4	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	200.00	X
5	REMOVE AND REPASTE STICKER ON AFFECTED AREAS	200.00	50
6	PANEL BEATING ON AFFECTED AREAS	1200.00	800
7	SPRAY PAINTING ON AFFECTED AREAS	1200.00	500
8	APPLY ANTI RUST ON AFFECTED AREAS	120.00	30

Subtotal 3300.00

Grand total 10026.90