

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

05/11/2020

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1

Veh # :- SKV4883X

Veh Model :- KIA FORTE K3 1.6A SX S/R HID

Estimate# :- CK421180

Claim # :-

ACC. Date :- 03/11/20

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	BOOT LID <i>4/</i>	1	PC 1,297.00	1,297.00 ✓
2.	BOOT LID HINGE RH & LH <i>X Svc</i>	2	PCS 66.00	132.00 X
3.	BOOT LID LOGO <i>re</i>	1	PC 30.00	30.00 ✓
4.	BOOT LID EMBLEM - FORTE <i>re</i>	1	PC 31.00	31.00 ✓
5.	BOOT LID REFLECTOR RH & LH - CHECK <i>? cm / (2 pcs) @ 696</i>	1	PC	1392 ✓
6.	BOOT LID LOCK <i>X Svc</i>	1	PC 109.00	109.00 X
7.	BOOT LID WEATHERSTRIP <i>X Svc</i>	1	PC 92.00	92.00 X
8.	TAILLAMP ASSY RH & LH - CHECK <i>? X Svc</i>	1	PC	
9.	REAR END PANEL <i>repair</i>	1	PC 266.00	266.00 X
10.	REAR END PANEL TOP COVER <i>? X Svc</i>	1	PC 56.00	56.00 X
11.	REAR BUMPER <i>cm</i>	1	PC 601.00	601.00 ✓
12.	REAR BUMPER REINFORCEMENT <i>? cm</i>	1	PC 304.00	304.00 ✓
13.	REAR BUMPER BRACKET RH & LH <i>? X Svc</i>	2	PCS 63.00	126.00 X
14.	REAR BUMPER RETAINER RH & LH <i>re</i>	2	PCS 28.00	56.00 ✓
15.	REAR BUMPER REFLECTOR LH - CHECK <i>? X Svc</i>	1	PC	
16.	REAR BUMPER LOWER GARNISH <i>? de</i>	1	PC 202.00	202.00 ✓
17.	REAR BUMPER CLIPS <i>re</i>	10	PCS 3.50	35.00 ✓
LIST TOTAL S\$				3,337.00
10% DISCOUNT S\$				-333.70
				3,003.30
SPECIAL NET ITEMS :				
1.	BOOT LID EMBLEM - K3 <i>re</i>	1	PC 30.00	30.00 ✓
2.	BOOT LID STICKER - C&C <i>re</i>	1	PC 25.00	25.00 ✓
3.	REVERSE SENSOR <i>?</i>	1	SET 200.00	200.00 X
SPECIAL NET TOTAL S\$				255.00
LABOUR :				
TO CUT/WELD REAR END PANEL. KNOCK AND STRAIGHTEN SPARE WHEEL PANEL. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION				
SPRAY PAINT BOOT LID, REAR END PANEL, SPARE WHEEL PANEL, REAR BUMPER, REAR BODY MEMBERS				
REMOVE & REFIT LUGGAGE COMPARTMENT INNER TRIM, GARNISH, COVERING				
REMOVE & REINSTALL REVERSE SENSOR AND CHECK FUNCTION				
RUST PROOF AFFECTED AREAS				
LABOUR TOTAL S\$				1,970.00

3553.20

55.00

1430.00

5038.20

20%

4030.56

1/8 - 4000

5 days

1430

3948.00

10%

3553.20

55

700 500 800.00

600 1,000.00

40 60.00

50.00

40 60.00

1,970.00

Estimate

05/11/2020

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1 139394
Veh # :- SKV4883X
Veh Model :- KIA FORTE K3 1.6A SX S/R HID
Estimate# :- CK421180
Claim # :-
ACC. Date :- 03/11/20
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 5,228.30

GST @ 7 % 365.98

AMOUNT DUE S\$ 5,594.28

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resurvey
Hp 90010068
5 days
4/3
16/11/2020 @ 1515
Resurvey after repair