

ASS. REC. BY:

REF: Al6 / 200 ~~2140~~ 1K qf3 <sup>12114</sup>

Kenneth

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Weggs

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. 2070138681

Claims No. 8199147121SG

Sum Insured: \_\_\_\_\_ Excess: 1100

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 8561c

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLE 77527 Yr Regn: 08, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or \_\_\_\_\_

Make: Honda Vezel c.c. 1496

Colour M.P. White A/C: Insured / Std / NI / NA

Sp. Reading 127539 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RUI 1171419

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NI / S/Rlm / STD / AB or

Tyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 2/11/20

Survey held at \_\_\_\_\_

Des. of Damages: FR Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Cecilia got handle OD claim ??</u>
<u>06/11/20 @ 9.57am</u>	<u>revert to Victor via Merimen</u>
<u>09/11/20 @ 9.47am</u>	<u>Victor informed C/A via Merimen</u>
<u>09/11/20 @ 3.44pm</u>	<u>Informed Ah Kwong C/A &amp; ex: \$550 by email</u>
	<u>Kenneth confirmed final fig \$6620.90, 5-days. (Red \$2943.70, 31%) (No Lump Sum)</u>

Date/Time, File Pass to?  : Prell. Report

1) 17/02 Typist  : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

\$ - RS - SI

Fixes

Others

TOTAL

Report Format: MER-OD

Lump Sum / I.B.I: (\$) 6620.90

# WEGA ENGINEERING PTE LTD

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721  
 Tel: 6452 1493 Fax: 6452 9153

GST Reg: 19-9900741 / Z

Claim Ref:


AIG Asia Pacific Insurance Pte. Ltd  
 78 Shenton Way, #11-16 Singapore 079120

Date : 03.11.2020

Vehicle No : SLE7752Z  
 Chassis No : RU11111419  
 Make/Model : HONDA VEZEL  
 Year : 2016

*MA*  
  
 Not Authorized  
 Resurvey & Repair  
 Selangor

S/N	Qty	Description	Cost	10%	Amount	
1	1pc	FRONT BONNET				
2	1pc	FRONT BONNET HIAGE LH	MA \$ 280.00	\$ 308.00		✓
3	1pc	FRONT BONNET HIAGE RH	R \$ 35.00	\$ 38.50		?
4	1pc	FRONT BONNET INSULATION	Sn \$ 35.00	\$ 38.50		X
5	1pc	FRONT BONNET RUBBER	Sn \$ 75.00	\$ 82.50		X
6	1pc	FRONT BONNET LOCK	Sn \$ 18.00	\$ 19.80		?
7	1pc	FRONT BUMPER	DIY \$ 75.00	\$ 82.50		✓
8	1pc	FRONT BUMPER TOWING COVER	BU Sn \$ 220.00	\$ 242.00		✓
9	1pc	FRONT BUMPER REFORCEMENT	Sn \$ 12.00	\$ 13.20		X
10	1pc	FRONT BUMPER RENTANNA LH	BU Sn \$ 220.00	\$ 242.00		✓
11	1pc	FRONT BUMPER RENTANNA RH	BU Sn \$ 15.00	\$ 18.00		✓
12	1pc	FRONT BUMPER LOWER SKIRT	Sn \$ 15.00	\$ 18.00		X
13	1pc	FRONT BUMPER LOWER GRILLER	BU \$ 180.00	\$ 198.00		✓
14	8pc	FRONT BUMPER CLIPS	\$ 48.00	\$ 52.80		?
15	1pc	FRONT FOG LAMP	MA \$ 16.00	\$ 17.60		✓
16	1pc	FRONT FOG LAMP COVER	\$ 145.00	\$ 159.50		?
17	1pc	FRONT RADIATOR BASE	\$ 18.00	\$ 19.80		?
18	1pc	FRONT RADIATOR OULER	\$ 220.00	\$ 242.00		?
19	2pc	FRONT GRILLER RADIATOR ( CHROME )	\$ 170.00	\$ 187.00		?
20	1pc	FRONT GRILLER EMBLEM " LOGO "	MA \$ 48.00	\$ 52.80		✓
21	1pc	FRONT HEADLAMP LH	MA \$ 18.00	\$ 19.80		✓
22	1pc	FRONT HEADLAMP RH	MA \$ 680.00	\$ 748.00		✓
23	1pc	FRONT HEADLAMP BRACKET LH	MA \$ 680.00	\$ 748.00		X
24	1pc	FRONT HEADLAMP BRACKET RH	CM \$ 24.00	\$ 26.40		✓
25	1pc	FRONT SUPPORT PANAL	Sn \$ 24.00	\$ 26.40		X
26	1pc	FRONT SUPPORT TOP GARNISH	\$ 350.00	\$ 385.00		?
27	1pc	FRONT SUPPORT TOP BRACKET	Sn \$ 48.00	\$ 52.80		X
28	1pc	FRONT RADIATOR AIR DUCT RH	\$ 48.00	\$ 52.80		?
29	1pc	FRONT RADIATOR AIR DUCT LH	\$ 22.00	\$ 24.20		?
30	1pc	FRONT AIR COND	\$ 22.00	\$ 24.20		?
31	1pc	FRONT RADIATOR	\$ 250.00	\$ 275.00		?
32	1pc	FRONT FAN COWLING	\$ 520.00	\$ 572.00		?
33	1pc	FRONT A/C FAN BI ADE	Sn \$ 66.00	\$ 72.60		X
34	1pc	FRONT RADIATOR BLADE	Sn \$ 45.00	\$ 49.50		X
35	1pc	FRONT A/C FAN MOTOR	Sn \$ 45.00	\$ 49.50		X
36	1pc	FRONT RADIATOR FAN MOTOR	Sn \$ 114.00	\$ 125.40		X
			Sn \$ 114.00	\$ 125.40		X

Wega Engineering Pte Ltd  
  
 Authorised Signature  
 Leong Chee Kwon  
 Mobile No: 84917768

LKKA Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

# WEGA ENGINEERING PTE LTD

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721  
 Tel: 6452 1493 Fax: 6452 9153 GST Reg: 19-9900741 / Z

Claim Ref:

AIG Asia Pacific Insurance Pte. Ltd  
 78 Shenton Way, #11-16 Singapore 079120

Date : 03.11.2020

Vehicle No : SLE7752Z  
 Chassis No : RU11111419  
 Make/Model : HONDA VEZEL  
 Year :

S/N	Qty	Description	Unit Price	Amount
Parts Total				<u>\$ 5,409.50</u>

**Labour Charges**

1	To check wiring & system function	\$ 100.00	20%
2	To remove n refix radiator , aircond condensor n fan system	\$ 280.00	?
3	To vacuum & charge aircon R134 gas	\$ 60.00	?
4	To inspect rear mechanisms & water test rear leaking	\$ 150.00	X
5	To flushing & top up radiator water coolant	\$ 80.00	?
6	To check headlamp lighting alignment	\$ 120.00	X
7	To replace , knocking accident front bonnet , bumper , support panal fender lh n rh	\$ 1,300.00	?
8	To respray front portion, bonnet , bumper , support panal n fender lh & rh	\$ 1,000.00	66%

Grand Total

\$ 8,499.50

Wega Engineering Pte Ltd

Authorised Signature  
 LIM HOCK GUAN  
 Mobile No: 9833 2798



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 718A

Vehicle Details

Vehicle No.: SLE7752Z  
Vehicle to be Exported: No  
Intended Deregistration Date: 05 Nov 2020  
Vehicle Make: HONDA  
Vehicle Model: VEZEL 1.5X CVT ABS D/AIRBAG 2WD  
Primary Colour: White  
Manufacturing Year: 2015  
Engine No.: L15B4031425  
Chassis No.: RU11111419  
Maximum Power Output: 96.0 kW (128 bhp)  
Open Market Value: \$20,484.00  
Original Registration Date: 01 Aug 2016  
First Registration Date: 01 Aug 2016  
Transfer Count: 1  
Actual ARF Paid: \$10,678.00

Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 31 Jul 2026  
PARF Rebate Amount: \$8,008.00

Intended COE Rebate Details

COE Expiry Date: 31 Jul 2026  
COE Category: A Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$52,301.00  
COE Rebate Amount: \$30,002.00  
Total Rebate Amount: \$38,010.00

The information contained herein is correct as at 05 Nov 2020

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 03/11/2020 15:42  
Date Of Accident 02/11/2020 14:45  
Exact Location Of Accident SEMBAWANG ROAD (NEAR MATA AYER RD)  
Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SLE7752Z  
Insured/Policyholder  
Name Of Registered Owner ANG SIU WAH  
NRIC No SXXXX718A  
Email Address SHIRAYUKI04@GMAIL.COM  
Mobile Phone No (LOCAL) +65-96834774  
Alternative Phone No OFFICE-96884774  
Vehicle Particulars  
Manufacturer HONDA  
Model VEZEL  
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE  
Are you claiming under your own insurance policy for repair to your vehicle? YES  
If No, Please state action to be taken  
Vehicle Category PRIVATE CAR  
Insurance Company  
Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number 2070138681  
Cover Note Number  
Driver  
Name of Driver ANG SIU WAH  
NRIC No SXXXX718A  
Date Of Birth 12/09/1950  
Occupation OUTDOOR  
Date Of Driving Pass 07/10/1981  
Driving Experience 39 YEARS AND 0 MONTHS  
Gender FEMALE  
Mobile Number (LOCAL) +65-96834774  
Fax Number  
Contact Number OFFICE-96884774  
Email Address SHIRAYUKI04@GMAIL.COM

Address BLK 467B ADMIRALTY DRIVE #03-143  
 Postcode 752467  
 Was driver an employee of the Insured's Company? NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle  
 Insurance Company of Driver's Own Vehicle

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

Please refer to Sketch Pan.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SJZ1372P  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver MR TOH  
 NRIC/Passport Number  
 Contact Number 86881114  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

SKETCH PLAN

JALAN MATA AYER

SAMBANGAN RD



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2/11/2020 Around 2:45 PM at Sambangan Road (Near Mata Ayer Rd)

I was driving my vehicle SLE 7752Z. And vehicle SJ 21372 P was in front of me. Accidentally I knocked against <sup>his</sup> car the back bumper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*Ang Lim Hel*  
 Policyholder's Signature  
 Date & Time: 3/11/2020

*Ang Lim Hel*  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 3/11/2020

*Leong*  
 Reporting Centre Personnel's Signature  
 Name: Tracia Leong  
 NRIC/FIN No.:  
 03 NOV 2020