

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	03 Nov 2020 17:49	Clm Veh Model Changed		[] Merimen Administrator
2	03 Nov 2020 17:49	Clm Created	Reg No: SLE7752Z. Policy No: 2070138681. Acct Date: 2020/11/02. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MLHM20096941	[I] Merimen Administrator
3	05 Nov 2020 13:46	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] LEE SU THING
4	05 Nov 2020 13:46	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] LEE SU THING
5	05 Nov 2020 13:46	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
6	05 Nov 2020 13:46	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/11/16	[A] LEE SU THING
7	05 Nov 2020 13:46	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] LEE SU THING
8	05 Nov 2020 13:46	Clm Registration Modified	Rep:1137->200899.	[A] LEE SU THING
9	05 Nov 2020 13:46	Clm Veh Model Changed	(204808) HONDA VEZEL 1.5 (A).	[A] LEE SU THING
10	05 Nov 2020 13:46	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] LEE SU THING
11	05 Nov 2020 17:57	Adj Rpt Initiated		[A] SHIAU CHAN
12	05 Nov 2020 17:57	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] SHIAU CHAN
13	05 Nov 2020 17:57	Clm Dtl Modified	JPJ Reg. Date: -> 2016/08/01.	[A] SHIAU CHAN
14	05 Nov 2020 17:57	Clm Details Notified		[A] SHIAU CHAN
15	06 Nov 2020 09:57	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2020/11/16	[A] SHIAU CHAN
16	06 Nov 2020 09:57	Adj Mandate Request	Cur.Req:6406.10:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
17	06 Nov 2020 12:28	Clm Registration Modified	Init.Est.:->5,000 - 6,000. Excess: -> 550.00. Excess Waived: -> 550.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Abu Kassim, Noor Mariesa
18	06 Nov 2020 12:28	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
19	09 Nov 2020 09:47	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/11/16. Mandate Remarks: Authorise repair. Bonnet, bumper why spray paint \$660? Labour? B/f paint with parts required. Re-inspection to be done for damage check and supplementary items / labour with clear photos.	[I] Koh, Victor-CK
20	09 Nov 2020 09:47	Adj Mandate Set	Approved:2633.60:Authorise repair. Bonnet, bumper why spray paint \$660? Labour? B/f paint with parts required. Re-inspection to be done for damage check and supplementary items / labour with clear photos. Reinsp:Yes.	[I] Koh, Victor-CK

Date From    Date To    Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
-------------	-----------	-----------	----------	----------	------------------	-------	-------	--------

2630325	05 Nov 2020 17:57:38	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLE7752Z		11.00
---------	-------------------------	--------------------------	-------	------------------------------------	---	----------	--	-------